CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
NORTHEAST Corner of Section 33 ,Township 108 N., Range 40 W., 5 th. P.M. STATE OF MINNESOTA, County of MURRAY At the corner location shown on the sketch: On			
		☑ On 6·27·85 placed a 1"x 6" RAIL	ROAD BOLT, DOWN O.I'
		SKETCH OF REFERENCE TIES	
		1 4	NAIL & DISC RLS 12967
			EAST SIDE GATE POST N12°E UP 1'
NAIL 8 DISC RLS.#12967	-0		
EAST SIDE POWER POLE			
Ψ UP 2' N 04° E ϕ	N 32°E 55.46'		
32.18	NAIL & DISC RLS#12967 WEST SIDE GATE POST		
\mathbb{N}	UP 1'		
CO. RD 15	CO. RD. 38		
	· — · — · • • • • • • • • • • • • • • •		
	/		
	NOTE:		
! !	MONUMENT IS ON & ROAD SOUTH		
 •	ON & E-W ROAD ON FENCE NORTH		
0 38	! 		
ا			
00	 		
BEARINGS OBSERVED WITH COMPASS			
Statement of evidence relative to this corner le	ocation is on back of page. J.B.M. 7-18-85 G-361		
I hereby certify that this document and the data OFFICE OF THE COUNTY RECORDER 72138			
I hereby certify that this document and the data contained herein was prepared by me or under	County of Murray		
my direct supervision.	I hereby certify that this document was filed in		
Levell R. Pounarecury 1 7-22-85	the Co. Recorders of fice at $\frac{10}{30 \text{th}}$.M. on the $\frac{30 \text{th}}{30 \text{th}}$ day of $\frac{\text{July}}{30 \text{th}}$ A.D., 19 $\frac{85}{30 \text{th}}$		
Registration No. 17005	County Recorder Alexing Ohne		
☐ Land Surveyor, ☐ Professional Engineer	By,Deputy		
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO		

Northeast Corner Section 33, Township 108 North, Range 40 West

This corner was originally established by the U. S. General Land Office survey in 1861. The government notes show corner marked with a wood post set in mound of earth with pits and trench dug around the mound.

In October 1984, the DNR Bureau of Engineering contacted the Murray County Offices of the Recorder and Highway Engineer for corner information.

The following information was obtained from the County Highway Engineer's Office:

Government corner tie book, (old) date not indicated, shows the corner to be a stone with these ties:

tack in fence corner, north on line, 32.8 feet RP tack in light pole, northwest, 36.8 feet

In October 1984, the DNR Bureau of Engineering traversed to the area of the corner and set a temporary point, a concrete nail, at the intersection of paved roads east-west and south and a fence line north. Checked the area for metal attraction and evidence of old ties but found nothing. The temporary point was found to be:

2631.24 feet from the north quarter corner of Section 33 5299.80 feet from the northeast corner of Section 34

Returned to the corner area on June 27, 1985, and dug a 12 inch diameter hole to a depth of 24 inches and probed down and around hole to a depth of 36 inches but found nothing. Center of hole was at above mentioned temporary point. Found new reference ties with RLS#12967 on them.

On July 17, 1985, talked with Gary Martin, RLS#12967, about the corner. Based on his conversation with the county engineer, who stated that road construction probably removed the stone, he accepts the concrete nail, at the intersection of roads and fence line as the location of the corner.

On June 27, 1985, the DNR Bureau of Engineering replaced the concrete nail with a 1 inch by 6 inch railroad bolt.

Traverse information is available from the DNR Bureau of Engineering.

rec17/missu2