index No
CERTIFICATE OF LOCATION OF GOVERNMENT CORNER
NUMBER 41 MEANDER Corner of Section 31 ,Township 108 N ,Range 40 W 5th Principal Meridian, State of Minnesota, County of MURRAY
Principal Meridian, State of Minnesota, County of
At the corner location shown on the sketch:
□ On found a
☐ left monument os found, ☐ lowered monument, ☐ removed monument (exploin)
■ On8/13/2008 Placed a 3/4" X 24" REBAR WITH PLASTIC CAP STAMPED
"MN DNR LS 17003", UP 0.1', FOR A REFERENCE MONUMENT
REFERENCE MONUMENT TO MC #41
ON TOP OF LAKE BANK
13.5' NORTH OF WESTERLY EXTENSION OF FENCE EAST
19.03'
19.03' S 89° 30' 03" E 573.32' MC #41 MC #41 19.03' S 89° 30' 03" E 573.32'
S 89° 30° 03 E (-(3132\≥) 70 (6 5) ≥
573.32'
MC #41
592.35'
MEANDER CORNER
MURRAY COUNTY COORDINATE SYSTÉM
NAD 1983 1996 ADJ.
N = 195130.961 E = 521234.349 BEARING IS COUNTY ORIENTATION
Statement of evidence for this corner location is on back of this page. 11/3/2008 SPK00220.00.00.01
I certify that this document was researched and prepared by me or under my direct supervision.
SIGNATURE
Title: 🔳 Land Surveyor 🔲 Professional Engineer 🗌 County Surveyor 🔲 County Engineer

Meander Corner Number 41 of Section 31, Township 108 North, Range 40 West, Page 1 of 3

The DNR Division of Lands and Minerals contacted the following for survey information:

Minnesota Secretary of State's Office

Murray County Recorder's Office

Murray County Highway Engineer's Office

Bueltel-Moseng Land Surveying of Marshall

Zieske Land Surveying Inc. of Windom

Madsen Land Surveying Inc. of Fairmont

Pellinen Land Surveying of Hutchinson

1861 U.S. General Land Office notes, obtained from the Secretary of State's Office, show the corner marked with a wood post with the following bearing trees marked:

10" W. Elm, North 3° East, 41 links (27.06 feet)

8" W. Oak, South 55° East, 59 links (38.94 feet)

The corner is also shown:

9.00 chains (594.00 feet) from the northeast corner of Section 6

31.00 chains (2046.00 feet) from the north quarter corner of Section 6

69.92 chains (4614.72 feet) from the northwest corner of Section 6

June, a plat of Subdivision of Gov. Lot No. 1 of Sec. 31, Twp. 108, Range 40, by J.W. Woolstencroft, County Surveyor, obtained from the County Recorder's Office, shows a point on the easterly edge of a meandered pond in the area of the corner. A description of what kind of monument was found or set at the point is not given. The point is shown:

603.2 feet from the northeast corner of Section 6

No information is given about the meander corner.

1936 A Survey Map by the National Park Service that shows Sections 5 and 6, T107N, R40W, Sections 1 and 2, T107N, R41W, and Sections 35 and 36, T108N, R41W, in the possession of the DNR Division of Lands and Minerals, shows that a base line was measured as follows:

from a brass plug at the intersection of a north-south concrete pavement road and an east-west gravel road in the vicinity of the northwest corner of Section 2, Township 107 North, Range 41 West to the area of the northeast corner of Section 5, Township 107 North, Range 40 West

No information is given about the meander corner.

A spike and lath were set on the north line of Section 6 between the north quarter corner of Section 6 and the northeast corner of Section 6 and are shown to be:

on the base line

Computations using stationing reveal the spike and lath are:

- a) 1320.00 feet from the north quarter corner of Section 6
- b) 1320.60 feet from the northeast corner of Section 6

Meander Corner Number 41 of Section 31, Township 108 North, Range 40 West, Page 2 of 3

The map has conflicting distances to section and quarter corners and appears that it's a preliminary survey because no boundary work is shown on it.

DNR Bureau of Engineering contracted N.C. Hoium and Associates Inc. of Coon Rapids, Minnesota, to survey property in Lake Shetek State Park. The DNR records of survey show that a traverse was run from the northwest corner of Section 1, Township 107 North, Range 41 West to the northeast corner of Section 5, Township 107 North, Range 40 West.

No information is given about the meander corner.

Computations from the survey information reveal that monuments were set on the north line of Sections 5 and 6 as follows:

3088 feet west of the northeast corner of Section 5

4826 feet west of the northeast corner of Section 5

5541 feet west of the northeast corner of Section 5

5860 feet west of the northeast corner of Section 5

A Conservation Monument was set on the north line of Section 6 at a distance of: 2170.70 feet east of the northwest corner of Section 6

1978 The plat of DIAMOND ROW in the Southeast Quarter of Section 31 by Willard Pellinen, LS 9626, obtained from the County Recorder's Office, shows an iron monument at the southeast corner of Section 31 (northeast corner of Section 6). Iron monuments are shown along the south line of Section 31 (north line of Section 6) at the following distances from the southeast corner of Section 31 (northeast corner of Section 6):

202.29 feet, 225.98 feet, 572.96 feet, 594.00 feet, 1484.96 feet, 1674.13 feet, 1699.81 feet

No information is given about the meander corner.

- 1981 December, a hand written statement with Willard Pellinen's business card copied thereon, from McCombs- Knutson Associates, Inc. in the possession of the DNR Division of Lands and Minerals, does not give any details about the meander corner. An attached sketch shows the following distances along the north line of Section 6:
 - a) 2561.60 feet from the northwest corner of Section 6 to the north quarter corner of Section 6
 - b) 2632.68 feet from the north quarter corner of Section 6 to the northeast corner of Section 6

Meander Corner Number 41 of Section 31, Township 108 North, Range 40 West, Page 3 of 3

Analysis of the above information along with the information in the Certificate of Location of Government Corner for the northeast corner of Section 1 led the DNR Division of Lands and Minerals to conclude that:

- a) in 1936, the National Park Service established the north line of Section 6 incorrectly
- b) in 1966/1967, N.C. Hoium and Associates Inc. established the north line of Section 6 incorrectly
- c) in 1981, Willard Pellinen used the correct method to establish the north line of Section 6 but in doing so he used an incorrect location for the east quarter of Section 12 to compute the location of the northwest corner of Section 6

Monuments that were set along the north line of Section 6 in 1936 and 1966/1967 were not searched for because their locations were determined from incorrect locations for the northwest corner of Section 6 (northeast corner of Section 1).

The location of the meander corner was computed lost and was found to be:

- a) in Park Lake
- b) 592.35 feet from the northeast corner of Section 6
- c) 4601.91 feet from the northwest corner of Section 6
- d) 2.84 feet north and 19.45 feet west of a found capped iron pipe marking a point on the south line of DIAMOND ROW

A field search was conducted for the GLO bearing trees but no evidence of them was found.

Accept the computed lost position as the location of the corner. A ¾ inch by 24 inch rebar with a plastic cap stamped "MN DNR LS 17003" was set on the north line of Section 6 as a reference monument to the corner as shown on the sketch of reference ties.