CERTIFICATE OF LOCATION OF GOVERNMENT CORNER							
NORTH QUARTER		_ Corner of Section	21	, Township	107N	_ , Range	39W
5th Principal Meridian, State of Minnesota, County of MURRAY							
At the corner location shown on the sketch:							
X	On 8/27/2020 found a NO. 3 REBAR WITHOUT CAP, 0.2' BELOW GRADE						
	X left monument as found □ lowered monument □ removed monument (explain)						
	Onplaced a _						
SKETCH OF REFERENCE TIES							
SKETGIT OF THE ENERGY THE							
CUT "X" IN NORTH END							
OF 12" RCP CULVERT ———————————————————————————————————							
N79°E — 11							
C.S.A.H. 11							
577°E 137.12'							
52.37 8.37						_	4
NAIL & BOTTLECAP IN NE				CUT "X" IN SOUTH END OF 12" RCP CULVERT			
FACE OF POWER POLE N.T.S.							
Statement of evidence for this corner location is on back of this page.							
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.			OFFICE OF THE COUNTY RECORDER				
,				County of Murray			
Signature Jon Jon			I here	I hereby certify that this			
			docui	document was filed in the Co.			
Date 6 (6) 2021 License No. 45874		Reco	Recorder's office atM. on the				
				day of		A.D. 20	
Title:			Coun	ty Recorder	2 2 2021	₽10W	$ \uparrow $
	Surveyor Profession	al Engineer	by_	JUN	r r 202		Deputy
□Count	ty Surveyor	gineer	DOC	UMENT NO.			

JASON LATZKE Minnesota License No. 45874

Statement of Evidence:

North Quarter Corner of Section 21, Township 107 North, Range 39 West, 5th Principal Meridian, Murray County, Minnesota.

July 1861 GLO Notes: Set post in mound

1963 Highway Department records show that a steel pin was placed (assumed) at the corner.

N&C in PP SE 51.62'
"X" in N end of pipe 134.72'

June 2012 Highway Department records show a $\frac{3}{8}$ " steel pin was located at corner. They listed the

coordinates: N: 179330.94 E: 561499.70

Sept. 2020 Westwood Professional Services searched and found a No. 3 rebar at the corner, as well as 2 ties

from 1963 Highway Department records. The coordinates fit well with 2012 Highway

Department records. I accepted the found monument.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.