| CERTIFICATE OF LOCATION  | OF GOVERNMENT CORNER   |
|--|--|
| NORTHEAST Corner of Section 1  | ,Township <u>106</u> ,Range <u>40</u> , <u>5TH</u> P.M.                              |
| STATE OF MINNESOTA, County of MURRAY                                       | · · · · · · · · · · · · · · · · · · ·  |
| At the corner location shown on the sketch:                                |  |
| □ On 07-11-2011 found a bent iron.   |  |
| ☐ left monument as found, ☐ lowered monument, ☒ removed monument (explain) |  |
| □ On 07-11-2011 placed a 1" pipe with seal #43844.                         |  |
| SKETCH OF REFERENCE TIES   |  |
|  |  |
|  |  |
| NORTH C  |  |
|  |  |
|  |  |
| Ø—————α<br>32.00'  |  |
| 32.00  |  |
|  | XA 70.05'  |
|  | 39.25'   |
| Minnesota State Plane Coordinate   |  |
| Nail and   | bottle cap in pedestal guard post SE 39.25' seal in utility pole West 32.00'         |
| N: 163448.678<br>E: 548389.332   |  |
| Statement of evidence relative to this corner location is on back of page. |  |
| I hereby certify that this document and the data                           | OFFICE OF THE COUNTY RECORDER  |
| contained herein was prepared by me or under                               | County of  |
| my direct supervision.   | I hereby certify that this document was filed in the Co. Recorders office atM on the |
| SIGNATURE 1/23/12  | day of JAN 2 5 2012 A.D. 20  |
| Registration No. <u>43844</u> ⊠ Land Surveyor, □ Professional Engineer     | County Recorder James V. Johnson  By , Deputy  |
| ☐ County Surveyor, ☐ County Engineer                                       | DOCUMENT NO  |
|  |  |

Andrew Parkers Andrews Andrews

## Statement of Evidence

In 1861, J. W. Myers did the original survey of the township lines.

On October 15, 1907, J. W. Woolstencraft measured the east line. He did not record a monument at the corner.

On December 29, 1989, the Murray County Highway Department recorded a white stone at the corner.

On July 11, 2011, Bueltel-Moseng Land Surveying found a bent iron at the corner. We removed the iron and probed for the stone. We did not find the stone. We used the ties from 1989 to reset the corner, it fell in the same spot as the bent iron. We set a 1" pipe with seal #43844 in place of the bent iron.