CERTIFICATE OF LOCATION OF GOVERNMENT CORNER  Northeast of Section 24 , Township 107N , Range 41W , 5th P.M.  STATE OF MINNESOTA, County of Murray  At the corner location shown on the sketch  On 9/30/08 found nothing.  I left monument as found lowered monument, removed monument (explain)	
On 10/06/08 placed a 5/8" Iron stake 16.24' West on North line of NE 1/4, actual corner is in Beaver Creek.	
SKETCH OF REFERENCE TIES  -Ne cor. sec. 24-107-41  (2636.0) (39.94 CH) (2637.60 M (2637.	
NE COR. COORDINATES 179332.56 N 516646.31 E MURRAY COUNTY COORDINATES NAD 83 (2007)	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.    Signature   10-23-08	I hereby certify that this document was filed in the Co. Recorder's Office at on the day of OCT 2 8 2008  County Recorder Amus V. Johnson By , Deputy DOCUMENT NO

## **Statement of Evidence**

Original Township Plat indicated the subdivision was surveyed by G.M. Fletcher with date of contract of July 11 1861. Original field notes indicated that a witness corner was placed at 150 links east of True Corner on line between Sections 18 and 19. Original fields notes on random line run East between Sections 13 and 24 indicates a distance of 80.88 chains to witness corner which states 100 links east of true corner but should be 150 links as previously stated. It also indicates that the North 1/4 Corner was set back 40.94 chains from Witness Corner or 39.44 from True Corner.

In 1970 the Minnesota Department of Natural Resources set a 3/4" Iron Pipe at a location Jerry Basset, property owner in Section 19, showed them where he thought it should be. They indicated that fence lines were projected from West, North & South which fit well with this location. We made a search of this area by using distance shown on DNR drawing of Section 18 and found nothing. This location was 20.5' West & 4.4' North of our calculated position. The location using DNR distances is West of Beaver Creek. I did not accept this position.

The true corner fell within the banks of Beaver Creek and is considered to be a lost corner.

Established corner midway and on line between Quarter Corners North and South as per surveying Instructions from U.S. Dept. of Interior, B.L.M. Actual distance vs. distances on original notes are very close as shown on Page 1 of 1.

Perry J. Zuss 10-23-08