CERTIFICAT	E OF LOCATION	OF GOVERN	MENT CORNER
NORTHEAST	Corner of Section	6,Township_107	1,Range 40 W, 5 th. P.M.
	, County of MURRAY		
At the corner location s			
☑ On 5-14-91	found a	NCRETE MONUME	NT WITH "+" IN
TC	P, DOWN 2.4' nument as found, D lower		
On 5-14-9	Y MARKER", OVER CO	NCRETE MONUME	MINUM CAP STAMPED NT. DOWN 0.3'
NOTE:	SKETCH OF R	EFERENCE TIES	
	DF & E-W ROAD JUITH FIELD DIVISION JUIN BOOK	NOISINIO	
_	TWP	RD.	
	— ŧ——·—	•	
_	 	<u>-`-</u>	
	s o6°E 40.15'		, þ
	DNR NAIL & DISC		''S 64 E 5 5 . 9 2 '
	TOP CENTER WOOD CORNER FENCE POST UP 4.8	×	DNR NAIL & DISC NE SIDE POWER POLE UP 4.6'
1983 MURRAY COUNTY COORDINATE SYSTEM N = 174,042.259		× BEARINGS OBSERVE	D WITH COMPASS
E = 543,078.247 Statement of evidence	relative to this corner loc		1.24.24.24
I hereby certify that the contained herein was possible. Muce Value Val	is document and the data repared by me or under 8-12-91 003 Professional Engineer	OFFICE OF THE Control of 1 hereby certify the the Co. Recorders of 2 day of 4	OUNTY RECORDER NURRAY 1 this document was filed in fice at M. on the
	□ County Engineer	DOCUMENT NO	

MINOR 1105 14 771

Northeast Corner of Section 26, Township 107 North, Range 40 West

The DNR Bureau of Engineering contacted the following for survey information:

Secretary of State's Office Murray County Recorder's Office and Highway Engineer's Office Chicago and North Western Railway Office in St. Paul Minnesota Department of Transportation Office in St. Paul

- 1861 U.S. General Land Office notes obtained from the Secretary of State's Office show the corner marked with pits and mound.
- Surveyor's Record Book A, page 77, obtained from the County Recorder's Office contains a survey by J. W. Woolstencraft. Survey shows a government stake and a 6" by 6" by 18" stone at corner. The corner is shown:

 40.26 chains (2657.16') from the north quarter corner of Section 25
- 1934 Surveyor's Record Book A, page 77, obtained from the County Recorder's Office contains corner information by F. A. March. A concrete stone is shown at corner but does not indicate if found or set. The following ties are shown to corner:
 - R.P. tack in corner fence post, south, 25.3 feet R.P. tack in fence post, southwest, 41.3 feet
- 1991 May, The DNR Bureau of Engineering hired a backhoe to dig for evidence of corner. A pointed 2" by 2" by 1' long rotten wood stake was found down 2'. Also, found a 5" diameter by 18" long concrete monument with a "+" on top down 2.4'. The wood stake was not found over the concrete monument. Searched for but found no evidence of the record ties. The concrete monument was found to be:

1 foot south of the center line of an east-west road in line with a fence south in line with a vague field division north 2657.62 feet from the north quarter corner of Section 25

Analysis of the above information led the DNR Bureau of Engineering to conclude that the found concrete monument marks the location of the corner. Discarded the rotten wood stake.