	CERTIFI	CATE OF LOC	ATION	OF GO	VERNME	NT COP	RNER		
NORTHEAST		Corner	of Section	4	, Township	107N	, Range	39W	
5th Princ	cipal Meridian, State	of Minnesota, County of	MURRAY						
At the co	orner location show	n on the sketch:							
X	On 8/27/2020 found a NO. 4 WITH BROKEN CAP. DOWN 0.2FT								
	X left monume	nt as found	☐ lowered	monument		emoved mon	ument (exp	elain)	
	On	placed a							
		SI	KETCH OF REF	FERENCE TIES	5				
		SE CORNER OF ELECTRICAL CABINET	SOON ZTOTH AVENUE		CENTER OF WAT	C.S.A.F			
	CENT	ER OF WATER GATE VALVE	3/34/3					N.T.S.	
		Statement of evidence	e for this corn	er location is	on back of this	page.			
prepai	red by me or under	locument was researched my direct supervision an nder the laws of the State	d that I am a	County I hereb	OF THE COUNTY ofMurray y certify that the ent was filed in	is	ER		
Signatu Date_	6/16/2021	License No. 458	374	Record	er's office at dav of				
Title:		_		County	Recorder		Srow	`	
_	Surveyor	Professional Engine	er	by		C C 2061		Deputy	
∐Coun	ity Surveyor	County Engineer		DOCU	MENT NO.				

JASON LATZKE Minnesota License No. 45874

Statement of Evidence:

Northeast Corner of Section 4, Township 107 North, Range 39 West, 5th Principal Meridian, Murray County, Minnesota.

No GLO Notes.

- 1913 June, Survey record for Section 3 shows a stone on south side of grade.
- 1980 October, Corner certificate filed by LS 12967 shows that a concrete monument was found and a $\frac{1}{2}$ " rebar with cap LS 12967 was set over it.
- 2013 August, Highway Department shows that a surveyor's cap and pin were located with coordinates: N: 195154.72 E: 564062.06
- 2020 September, Westwood Professional Services searched and found a No. 4 rebar with broken cap. Located about 1.5ft west of road intersection, per 1980 corner certificate. No other references were recovered. The coordinates fit those listed per 2013 Highway Department data. I accepted the found monument and set additional reference ties.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.