	CERTIFICATE OF LOCAT	ION	OF GO	/ERNME	NT CO	RNER	
NORTH	NEST Corner of Se	ction	25	, Township	107N	, Range_	40W
5th Princ	ipal Meridian, State of Minnesota, County of MU			,			
At the co	rner location shown on the sketch:						
X	On 8/26/2020 found a REBAR WITH 1" ALUMINUM "DNR" CAP						
	X left monument as found						plain)
	Onplaced a						
	SKETCI	H OF REF	ERENCE TIES				
NO.3 REBAR WITH REF. CAP							
	N680 40.32	'n	141ST STREET				
577°W 572°E 39.24							
	NO.3 REBAR WITH REF. CAP		NO.3 REBAR WITH REF. CAP			-	
							N.T.S.
Statement of evidence for this corner location is on back of this page.							
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.			OFFICE	OF THE COUN	ITY RECORD	PER	
Signati	ire	_	I hereby	certify that the cent was filed in cer's office at	is the Co.	1. on the	
Date Title:	License IVO.		County	day of	aven Br	1.D. 20 1M_	
X Land	Surveyor Professional Engineer		by JU	N 2 2 202	11		, Deputy
$\Box_{Coun}$	ty Surveyor 🔲 County Engineer		DOCUM	1ENT NO			

## JASON LATZKE Minnesota License No. 45874

## Statement of Evidence:

Northwest Corner of Section 25, Township 107 North, Range 40 West, 5th Principal Meridian, Murray County, Minnesota.

The DNR Bureau of Engineering contacted the following for survey information:

Secretary of State's Office

Murray County Recorder's Office and Highway Engineer's Office

Chicago and North Western Railway Office in St. Paul

- 1861 U.S. General Land Office notes obtained from the Secretary of State's Office show the corner marked with pits and mound.
- Surveyor's Record Book A, page 77, obtained from the County Recorder's Office contains a survey by J.W. Woolstencraft. Survey shows a fovernment stake and a 6" by 6" by 18" stone at corner. The corner shown: 40.26 chains (2657.16') from the north quarter corner of Section 25.
- 1934 Surveyor's Record Book A, page 77, obtained from the County Recorder's Office contains corner information by F.A. March. A concrete stone is shown at corner by does not indicate if found or set. The following ties are shown to corner:

R.P. tack in corner fence post, south, 25.3 feet

R.P. tack in fence post, southwest, 41.3 feet

1991 May, The DNR Bureau of Engineering hired a backhoe to dig for evidence of comer. A pointed 2" by 2" by 1' long rotten wood stake was found down 2'. Also, found a 5" diameter by 18" ling concrete monument with a "+" on top down 2.4'. The wood stake was not found over the concrete monument. Searched for but found no evidence of the record ties. The concrete monument was found to be:

1 foot south of the centerline of an east-west road

in line with a fence south

in line with a vaque field division north

2657.62 feet from the north quarter corner of Section 25

Analysis of the above information led the DNR Bureau of Engineering to conclude that the found concrete monument marks the corner. Discarded the rotten wood stake.

2020 Westwood Professional Services searched and found iron with DNR cap per 1991 corner certificate. Set new reference ties.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.