Index No.
RNMENT CORNER
_ Range <u>42, 5TH</u> P.M.
TE FENCE RUNNING WESTERLY. removed monument (explain)
S
FIELD
PED
N: 667,316.26 E: 2,112,516.46 MN SOUTH ZONE NAD 83 NOT TO SCALE

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
WEST 1/4 Corner of Section 7. Township 105. Range 42. 5TH P.M.		
STATE OF MINNESOTA, County ofMURRAY		
At the corner location shown on the sketch :		
On 3/21/2006 found A REBAR WITH AN UNREADABLE CAP.		
ON THE EAST SHOULDER OF THE ROAD, OPPOSITE FENCE RUNNING WESTERLY. left monument as found, lowered monument, removed monument (explain)		
On set		
Sketch of reference ties		
3 LI		
-N- FIELD HWY 91 ASPHALT ROAD APPROACH	NO1.32,32,"E 2632.41 Light State of the company o	
WOOD FENCE POST		
FIELD M.S. 10S		
ELECTRICAL TRANSFORMER D MEASURED FROM TOP	PRIVATE APPROACH	
MEASURED FROM TOP NE CORNER BOX HWY 91 ASPHALT ROAD	TPD MEASURED FROM TOP CENTER TP BOX	
Statement of evidence relative to this corner location is on back page		
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.	OFFICE OF THE COUNTY RECORDER County of SEP 2 8 2006	
30 6/29/06	I hereby certify that this document was filed in the Co. Recorders office atM. on the day of A.D., 20 County Recorder amus V. Johnson	
X Land Surveyor, Professional Engineer	By, Deputy	
County Surveyor, County Engineer DOCUMENT NO.		

WEST 1/4 CORNER, SECTION _7 , T. 105 N., R. 42 W., MURRAY COUNTY, MINNESOTA

1861

J.W. Myers, US. Deputy Surveyor, monumented corner.

? Date

MN DOT R/W Map for Trunk Highway 91, sheet 7/14, retracement calls for a 30" concrete monument in place; replacement certificate dated: 01/30/1953; at the intersection of N-S road and fence running westerly.

Ties: NE-63.92' to telephone pole; SW-49.19' to disc in culvert; NW-55.0' to disc in culvert; W-73.38' to fence post.

10/05/1976

Murray Co., found a concrete monument and placed an iron pin above the monument.

Ties: SW-60.35' to nail & cap on a power pole; SE-86.9' to a nail & cap on a power pole; NW-58.18' to a nail & cap on a power pole.

5/27/1993 Murray Co., placed a PK nail in the asphalt, above the corner.

3/21/2006

Ulteig Engineers, Inc., Survey Crew, Brian Payne Party Chief found a rebar with an unreadable cap at the 1/4 corner.

Ties: S-149.6' to top, center of telephone pedestal;

SW-148.9' to NE corner of electrical transformer box;

W-106.8' to PK nail in wood, fence post; N-2632.41' to NW corner, Section 7; S-2636.05' to SW corner, Section 7.