CERTIFICATE OF LOCATION OF GOVERNMENT CORNER
NORTH QUARTER Corner of Section 17 ,Township 107 ,Range 42 ,5TH P.M
STATE OF MINNESOTA, County of MURRAY
At the corner location shown on the sketch:
☑ On 04-17-2008 found a SPIKE
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)
On 04-17-2008 placed a 5/8" IRON WITH SEAL #43844
SKETCH OF REFERENCE TIES
Minnesota State Plane Coordinate System Murray County Datum Nail and seal in corner fence post East 50.05' NAD83 (1996) Nail and seal in corner fence post East 50.05' Spike West 200'
NAD83 (1996) Spike West 200' N: 184777.361 Southeast corner of power box NW 59.92' E: 461344.581
Statement of evidence relative to this corner location is on back of page.
I hereby certify that this document and the data OFFICE OF THE COUNTY RECORDER contained herein was prepared by me or under County of
I hereby certify that this document was filed in the Co. Recorders office atM on the
871
Modern Surveyor, ☐ Professional Engineer By UC 1 2 2 2008 U , Deputy ☐ County Surveyor, ☐ County Engineer DOCUMENT NO

Statement of Evidence

In 1861, L. G. M. Fletcher, did the original subdivision of the township.

On June 26, 1902, 2 stones were recorded at the corner.

The Murray County Highway Department set a concrete stone and tied it out.

In 1963, The Murray County Highway Department found the stone, and placed an iron pin there in 1965.

On April 19, 1989, The Murray County Highway Department dug for the monument and found nothing, they placed a $\frac{3}{4}$ " rebar and tied it out.

On April 17, 2008, Bueltel-Moseng Land Surveying found a spike at the road surface. We were able to check to the Murray County Highway Department ties from April 20, 1989. We replaced the spike with a $\frac{5}{8}$ ⁿ iron with seal #43844.