| CERTIFICATE OF LOCATION | OF GOVERNMENT CORNER |
|---|---|
| NORTHEAST Corner of Section 4 | ,Township <u>107</u> ,Range <u>39</u> , <u>5TH</u> P.M. |
| STATE OF MINNESOTA, County of MURRAY | |
| At the corner location shown on the sketch: | |
| On 6/4/2024 found a <u>iron with broken cap over a concrete monument. Ties are go</u> od. | |
| ☑ left monument as found, ☐ lowered monument, ☐ removed monument (explain) | |
| □ On placed a | |
| SKETCH OF REFERENCE TIES | |
| SKETCH OF REFERENCE TIES SE CORNER ELEC. BOX MONUMENTS FOUND BROKEN SCALE C.S.A.H. #14 - 181ST STREET Murray County Coordinate System NAD83 (1996) N: 195154.710 SKETCH OF REFERENCE TIES WW MATER VALVE WATER VALVE WATER VALVE WGS84 LAT:44*06'31.6923" | |
| E: 564062.056 LON:-95*31'22.0392" Statement of evidence relative to this corner location is on back of page. | |
| | |
| I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. Daniel L. Bueltel License No. 43844 | MAR 13 2025 Karen Brann MARPAY COUNTY PERMANER |

Statement of Evidence

NORTHEAST CORNER SECTION 4, T107N, R39W of the 5th P.M.

In July of 1861, J.W. Myers layed out the original township lines.

On September of 1861, L. Brockmann did the original township subdivision.

In June 22, 1913 a survey by J.W. Woolstencroft notes a stone at the corner, the stone being on the south side of the grade of the road.

1940 - County records show a concrete monument.

On October 9, 1980 Gary Martin, LS 12967, found a concrete monument and placed a $\frac{1}{2}$ " iron with seal #12967 over top of the concrete monument.

County records from August of 2013 show an iron with a suveyors cap at the corner.

In September 2020 Westwood Professional Services searched and found a No. 4 rebar with a broken cap. Located about 1.5 ft west of road intersection.

On June 4, 2024 Bueltel-Moseng Land Surveying found a $\frac{1}{2}$ " iron with a broken cap. Iron is 1.5' west of road intersection.