


SURVEYOR'S RECORD

Section 20

Township 107

Range 40



20
21

Feb. 5 - 1934


"B" concrete stone with +; R.P. Tack in
 cor. fence post N.E. 473; R.P. Tack in
 tel. pole N.E. 492; R.P. Hub. S.W. N. 502'
 "C" concrete stone with +; R.P. Tack
 in fence post S.E. 307; R.P. Tack
 in fence post S.W. 384;
 "H" concrete stone with +; Tack in
 tel. pole S.E. ~~473~~^{42.3'} R.P. Tack in cor.
 fence post S.W. 494'
 "I" concrete stone with R.P. Tack
 in cor. fence post Easton line 336
 R.P. Tack in fence post N.E. 441'

7.9. March

"D" : R.P. Tack in Light pole SW 425; R.P. Tack in Light Pole NW 432
 "E" "Concrete Stone" : R.P. Tack in Tree SW 665; R.P. Tack in Tree SE.
 452; R.P. Tack in Cor. fence post Easton Line 302; R.P. Tack in
 Gate post NE. ~~374~~³³¹

"I" Placed Iron Pin Sept 29, 1969 D.T.
 R.P. N+C in T.P. S.W. 68.5
 R.P. N+C in P.P. S.E. 64.45

SURVEY No. _____
 Section 20 Town 107 Range 40



FIELD NOTES.

February 5, 1934

- "B" - Concrete stone with +; R.P. Tack in corner fence post N.E. 42.3'; R.P. Tack in del. pole N.E. 49.9'; R.P. Hub S.W. + N.W. 50.0'.
 "C" - Concrete stone with +; R.P. Tack in fence post S.E. 30.7'; R.P. Tack in fence post S.W. 38.1'.
 "H" - Concrete stone with +; Tack in del. pole S.E. 42.5'; R.P. Tack in cor. fence post S.W. 49.4'.
 "I" - Concrete stone with +; R.P. Tack in corner fence post East on line 33.6'; R.P. Tack in fence post N.E. 44.1'

J. A. March