

# MURRAY COUNTY.


Section 23

Township 105

Range 42

10798 McGill-Warner Co., Blank Book Manufacturers, St. Paul.

FENTON



1936

"B" "STONE" R.P. TACK IN CORNER FENCE POST S.W. 45.1' ; R.P. TACK IN CORNER FENCE POST 54.8'

"C" STONE R.P. TACK IN CORNER POST SOUTH 33.7' R.P. TACK IN FENCE POST S.W. 57.5'

"D" "STONE" TACK IN CORNER POST NORTH ON LINE 33.2' R.P. TACK IN CORNER FENCE POST

S. E. 46.6'

April 1971

N&C in R.P. SE 56.62' , N&C in C.F.P. NW 61.65'

"B" Stone with iron + abuse N&C in C.F.P. SW 68.59'

"4" Placed steel pin over cone monument 6" below new gravel surface. June 1973: R.P. Chisled "x" painted red top rib south end & culv. Sta. 26+45 Southwesterly 42.20'; R.P. Chisled "x" top rib north end & culv. Sta. 26+45 Northwesterly 46.31'; R.P. chisled "x" on metal bracket top east end Fe.E. Culv. Northeast 43.43'.

"F" Placed cone monument over existing stone w/ slanted steel pin 0.5' below new gravel surface. June 1973: R.P. N&C, R.P. SE. 58.60'; R.P. steel pin & TWP road north 100.0'; R.P. steel pin & TWP road south 200.0'.


"I" Placed bridge spike over 2x2 hub N&C End brace Post S.E. 63.62' N&C End brace Post S.W. 51.60' N&C brace Post N.W. 57.58'

22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36

SURVEY No. \_\_\_\_\_

Section 23 Town 105 Range 42

B



H

FIELD NOTES.

B Stone fence cor. 56.7 N.W. Cor. 45.1 SW. Cor. 46.5 SE

H Stone fence cor. 41.8 NE. - Cor. 40.0 NW. - Cor. 42.5 SW.

1 Stone fence cor. 31.0 West on line