

MURRAY COUNTY.

Section 31
 10798 McGill-Warner Co., Blank Book Manufacturers, St. Paul.

Township 105

Range 41




B T.P. 312' S.E. F. cor 390' S.E. F. cor. 392' N.E. F. cor 366' N.W. June 1971 Placed R.R. Spike over Conc. Mon. N. in B.C. Top of Cor. Fe. Post 49.58' N.W.
 F. cor. 360' S.W.
 G "Concrete Stone" : R.P. Tack in Cor fence post North 36° : R.P. Tack in Gate post N.W. 43°
 H "Concrete Stone" : R.P. Tack in Blazed fence post South 33° : R.P. Tack in Blazed fence post S.W. 45°
 I "Concrete Stone" R.P. Tack in Cor. fence post East on Line 33° : R.P. 1971 Placed R.R. Spike over Conc. Monument
 Tack in Race post S.E. 48°
 D "Found Stone 10' below road top June 1971, Placed R.R. Spike over stone
 N. in B.C. T.P. 27.25' East
 N. in B.C. in Gate Post 33.55' N.E.
 N. in B.C. in Wood Fe. P. 52.50' N.
 N. in B.C. 5 side Cor. Fe. P. 33.66' East.
 N. in B.C. 2nd P. S. of C.P. 41.72' S.E.
 N. in B.C. 4 side P.P. 46.78' S.W.
 N. in B.C. Top of Cor. Fe. Post 49.58' N.W.
 N. in B.C. C.P. 34.28' East
 N. in B.C. 1st Fe. P. S. of Cor. Post 43.36' S.E.
 1st Steel Fe. Post S. of Marker Post - 40.65' S.W.
 1st Steel Fe. Post N. of Cor. Post - 43.45' N.E.
 N. in B.C. 2nd Fe. Post 5.58.00' S.W.

30
 31
 32
 33
 34
 35

SURVEY No. _____

Section 31 Town 105 Range 41

B



FIELD NOTES.

B T.P. 315 SE. F 39.0 SE. F. Cor. 39.7 N.E. F 36.6 N.W. F 36.0 SW