


MURRAY COUNTY.

Section 5
 10798 McGill-Warner Co., Blank Map Manufacturers, St. Paul.

Township 105

Range 39

Sec 6
 16' shot
 F 273



- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15
- 18
- 19
- 20
- 21
- 22
- 23
- 24
- 25
- 26
- 27
- 28
- 29
- 30
- 31
- 32
- 33
- 34
- 35
- 36

Aug 11 1926
 1934
 "E" Stone: R.P. Tack in Blazed fence post 5E. 342'; R.P. East side of West Concrete post 338'. 2' sub cut, No Stone, R.P. Mored, 50' R.W., 1972
 "D" Stone: R.P. NE Cor. of SW Concrete post @ base 462'; R.P. Tack in Blazed Light pole NW. 42.5'. 1972 sub cut on plan, No Stone, R.P. mored, 50' R.W.
 "I" Located Field Stone 2' Below Fin. Grade Mar. 27, 1975: R.P. N&C. 49. NW. 36.80; R.P. 2nd steel Fence Post From Cor. Post (Painted Red) E. 71.40
 "H" Conc. Monument 1.3' Below Gravel Surface, Mar. 27, 1973 (See Sect. 7)
 "B" Located Field Stone 2.6' Below Gravel Surface Mar. 27, 1973: R.P. N&C R.P. NE 49.36; R.P. N&C TR. NW. 58.08

SURVEY No. _____

Sec 6
16' short
F 273
Section #6
45' in
Sta in 1145 Line

5

Town

10
F 2905

Range 39



FIELD NOTES.

Aug 11, 1926