CERTIFICATE OF LOCATION OF GOVERNMENT CORNER  East $1/4$ of Section $24$ , Township $107N$ , Range $41W$ , 5th P.M.  STATE OF MINNESOTA, County of Murray  At the corner location shown on the sketch  On $10/6/08$ found strong signal above iron stake    On $10/6/08$ found   lowered monument,   removed monument (explain)	
placed d_survey marker spixe with disc name: 25000	
SKETCH OF 1  98 00 HYS 33  EAST 1/4 COR. SEC. 24-104-41  69,73  5/8" IRON STAKE	REFERENCE TIES  MAG NAIL IN CM CULV.
	E 1/4 COR. COORDINATES 176695.39 N 516651.78 E MURRAY COUNTY COORDINATES NAD 83 (2007)
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.  Levy L. Jeske 10-23-08  SIGNATURE DATE  MN. LICENSE NO. 23008  Land Surveyor, Professional Engineer  County Surveyor, County Engineer	I hereby certify that this document was filed in the Co. Recorder's Office at on the day of OCT 2 8 2008  County Recorder ames V. Johnson By , Deputy DOCUMENT NO

## **Statement of Evidence**

10-23-08

Original Township Plat indicated Township lines were surveyed by J.W. Myers with date of contract of June 22<sup>nd</sup> 1861 and subdivision was surveyed by G.M. Fletcher with date of contract of July 11 1861.

Murray County Highway Department records indicate an iron pin was placed in 1969 and found again in 1989. In 1994 they removed iron pin and dug a 2' X 4' X 4' deep hole and also probed and found nothing, they then replaced iron pin.

On 10/6/08 we found a strong signal that fit County ties reasonably well. We placed survey marker spike with disc number 23008 and established new ties.

PAGE 2 OF 2