

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 7, Township 107 N, Range 39 W, 5th P.M.

STATE OF MINNESOTA, County of MURRAY


At the corner location shown on the sketch

- On _____ found a _____
- left monument as found, lowered monument, removed monument (explain)
- On 10-9-91 placed a 3/4" x 24" REBAR WITH ALUMINUM CAP STAMPED
"DNR SURVEY MARKER", DOWN 0.4'

SKETCH OF REFERENCE TIES



NOTE:
 MONUMENT IS
 ON N-S ROAD
 16.5' SOUTH OF FIELD ROAD EAST
 IN LINE WITH FENCE LINE E-W



1983 MURRAY COUNTY
 COORDINATE SYSTEM
 N = 187,263.100
 E = 553,508.407

DNR NAIL & DISC
 SE SIDE POWER POLE
 UP 3'

BEARING OBSERVED WITH COMPASS

Statement of evidence relative to this corner location is on back of page

J.B.M. 11-19-91
 WMA 00065.00.00.01

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Bruce W. Sheppard 12-2-91
REGISTERED SURVEYOR DATE

Registration No. 17003

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER
 County of MURRAY

I hereby certify that this document was filed in the Co. Recorder's office at _____ M. on the _____ day of _____ A.D., 19__

County Recorder James V. Johnson
 By DEC 4 1991, Deputy

DOCUMENT NO. _____

East Quarter Corner of Section 7, Township 107 North, Range 39 West

The DNR Bureau of Engineering contacted the following for survey information:

Minnesota Secretary of State's Office
Murray County Recorder's Office
Murray County Highway Engineer's Office

1861 U.S. General Land Office notes obtained from the Secretary of State's Office show the corner marked with pits and mound.

1991 October, DNR Bureau of Engineering hired a backhoe to dig for evidence of a monument at corner. Dug a 4 foot east-west by 15 foot north-south by 3 foot deep hole the center being on the center line of a north-south road and in line with fences east and west. No evidence of a monument was found. Set a DNR Survey Marker on the center line of the north-south road and in line with fences east and west and found it to be:

2673.88 feet from the northeast corner of Section 7

2631.69 feet from the northeast corner of Section 18

21.07 feet south and 4.50 feet east of the computed lost position for corner

Analysis of the above information led the DNR Bureau of Engineering to conclude that the intersection of the center line of the north-south road and fence lines east and west marks the obliterated position of the corner.