	CERTIFI	CATE OF	LOCATION	OF GO	OVERNME	NT COP	RNER		
EAST QUARTER			_ Corner of Section	9	, Township	107N	, Range	39W	
5th Principal Me	ridian, State	of Minnesota, (County of MURRAY						
At the corner loc	cation shown	on the sketch:							
☑ On _	On8/27/2020 found a NO. 4 IRON WITH CAP LS#44996 "BHI", DOWN 0.2FT								
$oxed{X}$ left monument as found $oxed{\Box}$ lowered monument $oxed{\Box}$ removed monument								lain)	
□ On _	DATE	placed a_							
:			SKETCH OF RE	FERENCE T	TIES				
	T-POST W/	WHITE PLASTIC	STEENE STORY W. S.S.S.	7. 3.8.5 - 3.8.6.5 - 3.8.6.5 - 3.8.6.7 AVENUE					
NO. 3 REBAR WITH REF. CAP					NO. 3 REBAR WITH REF. CAP N.T.S.				
Statement of evidence for this corne I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.				OFFIG 2. Cour	OFFICE OF THE COUNTY RECORDER County ofMurray				
Signature Date6/16	Jan (License N	lo. <u>45874</u>	docu	eby certify that the ment was filed in rder's office at day of	the Co. M. _A.	D. 20		
Title: X Land Surveyo	or.	Profession	nal Engineer	by	JUN 2			Deputy	
County Surve		County En	•		UMENT NO.			copuly	

JASON LATZKE Minnesota License No. 45874

Statement of Evidence:

East Quarter Corner of Section 9, Township 107 North, Range 39 West, 5th Principal Meridian, Murray County, Minnesota.

- 1861 July, This corner was not set. Meander corner were set North and South of the corner.
- 2019 December, A survey in Section 9 by Jesse Zeig shows that he set a $\frac{1}{2}$ iron and cap LS #44996 at the corner.
- 2020 September, Westwood Professional Services searched and found an iron with cap LS #44996 at the corner. Accepted the found monument and set reference ties.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.