CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
NORTH QUARTER Corner of Section 1 ,Township 105 N , Range 39 W , 5 th P.M.	
STATE OF MINNESOTA, County ofMURRAY	
At the corner location shown on the sketch:	
On found a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
On 5-6-76 placed a 1/2"x18" IRON PIPE DATE	
SKETCH OF REFERENCE TIES	
1 /	
1]	
-N- 	
NAIL & BOTTLE CAP NE SIDE OF GATE POST	
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	xxxxxx.
29.97'	
TWP RD.	
30.23	
··.	. 33.04
NAIL & BOTTLE CAP	NAIL & BOTTLE CAP
NW SIDE OF FENCE POST	NE SIDE OF FENCE POST
NOTE: MONUMENT IS	
2.4' NORTH OF & E-W ROAD	
Carterina of a idense relative to this increase location is an back of page J.B.M. 3-25-85	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE COUNTY RECORDER County of
my direct supervision.	I hereby certify that this document was filed in
Bruce W. sherred 12/20/85	the Co. Recorders office atM. on the day of A.D., 19
Registration No. 17003	County Recorder
■ Land Surveyor, □ Professional Engineer	By,Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO.

North Quarter Corner Section 1, Township 105 North, Range 39 West

This corner was originally established by the U. S. General Land Office survey in 1861. The government notes show:

set post, drove charred stake, made mound of earth and sod with trench and pits as per instructions.

In October 1975, the DNR Bureau of Engineering contacted the following for corner information:

Murray County Offices of the Recorder and Highway Engineer Sioux Engineering of Windom

The following information was obtained from the County Recorder's Office:
A Surveyor's Record Book, contains a survey done in 1903, surveyor
not indicated. Survey shows the government mound and stake at corner
2642.5 feet from the northwest corner of Section 1.

In January 1976, the DNR Bureau of Engineering traversed to the area of the corner and set a temporary point on the center line of an east-west road in line with a fence north. The temporary point was found to be:

2640.60 feet from the northeast corner of Section 1

2645.91 feet from the northwest corner of Section 1

2.4 feet south of a line from the northeast corner of Section 1 to the northwest corner of Section $\mathbf{1}$

Then a position for corner was computed on a line from the northeast corner of Section 1 to the northwest corner of Section 1 and in line with fence north.

Accept the computed position as the location of the corner.

Traverse information is available from the DNR Bureau of Engineering.

73hab