NORTH QUARTER Corner of Section 1 ,Township 106 ,Range 40 ,5TH P.  STATE OF MINNESOTA, County of MURRAY  At the corner location shown on the sketch:  On
At the corner location shown on the sketch:  On found a  left monument as found,   lowered monument,   removed monument (explain)  On 17-29-2011 placed a 1" pipe with seal #43844.  SKETCH OF REFERENCE TIES
On
DATE  ☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)  ☐ On 07-29-2011 placed a 1" pipe with seal #43844.  SKETCH OF REFERENCE TIES
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)  On 07-29-2011 placed a 1" pipe with seal #43844.  SKETCH OF REFERENCE TIES
On 07-29-2011 placed a 1" pipe with seal #43844.  SKETCH OF REFERENCE TIES
SKETCH OF REFERENCE TIES
HE TO THE REPORT OF THE PARTY O
27.45'
FIELD ROAD
Minnesota State Plane Coordinate
System Murray County Datum NAD83 (1996)
N: 163460.856 Nail and survey marker in lone wood post SW 27.45' E: 545767.035
Statement of evidence relative to this corner location is on back of page.
I hereby certify that this document and the data OFFICE OF THE COUNTY RECORDER contained herein was prepared by me or under County of
my direct supervision. I hereby certify that this document was filed in
the Co. Recorders office atM on th
Registration No. 43844  County Recorder James V. Johnson
🛮 Land Su <b>rv</b> eyor, 🗆 Professional Engineer By
☐ County Surveyor, ☐ County Engineer ☐ DOCUMENT NO.

The state of the s

## Statement of Evidence

In 1861, J. W. Myers did the original survey of the township lines.

On July 29, 2011, Bueltel-Moseng Land Surveying set a 1" pipe with seal #43844 midway and on line between the section corners. It fell  $3'\pm$  east of the field road.

The state of the s