	CERTIFI	CATE OF	LOCATION	OF GO	VERNME	NT CC	RNER		
NORTH QUARTER			Corner of Section	12	, Township	107N	_ , Range	40W	
5th Principal Meridian, State of Minnesota, County of MURRAY									
At the cor	ner location showr	on the sketch:							
X	On <u>8/26/2020</u> found a <u>REBAR WITH CAP JOHNSON LS 50343 DOWN 0.3FT</u> DATE								
	$oxed{X}$ left monument as found $oxed{\Box}$ lowered monument $oxed{\Box}$ removed monument (exp						olain)		
	Onplaced a								
	SKETCH OF REFERENCE TIES								
		TOP	N SIDE 15IN CMP SET NO3 N66°E 36.46			\circ	RB W/ REF CAP		
							171ST A	VE	
	TOP S SIDE 15IN CMP							N.T.S.	
Statement of evidence for this corner location is on back of this page.									
I hereby certify that this document was researched and prepared by me or under my direct supervision and the licensed Land Surveyor under the laws of the State of N			ision and that I am a	County	OFFICE OF THE COUNTY RECORDER County of				
Signatur Date <u>6</u> Title:	1/16/2021	License No.	45874	docum Record	ent was filed in ler's office at day of Recorder	the Co.	M. on the A.D. 20		
X Land S	urveyor	☐ Professiona	l Engineer	by	JUN 2 2	2021		Deputy	
□ County	/ Surveyor	☐ County Eng	ineer	DOCU	MENT NO.				

JASON LATZKE Minnesota License No. 45874

Statement of Evidence:

North Quarter Corner of Section 12, Township 107 North, Range 40 West, 5th Principal Meridian, Murray County, Minnesota.

GLO - JULY, 1861 SET POST IN MOUND

APRIL 25, 2017 - CORNER CERTIFICATE FILED BY LS 50343 SHOWS THAT THEY DUG WITH A BACKHOE AND FOUND A STONE OVER ANOTHER STONE. SET 5/8" IRON WITH SEAL #50343 OVER THEM. MURRAY COUNTY COORDINATES N 189870.22 E 545729.52.

SEPTEMBER 2020 - WESTWOOD PROFESSIONAL SERVICES SEARCHED AND FOUND A REBAR WITH CAP #50343 PER 2017 CORNER CERTIFICATE. I ACCEPTED THE FOUND MONUMENT AND ESTABLISHED ADDITIONAL REFERENCES.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.