	Index No.
CERTIFICATE OF LOCATION	ON OF GOVERNMENT CORNER
NORTH 1/4 Corner of Section 15	5. Township <u>106N.</u> Range <u>43W</u> , <u>5TH</u> P.M.
STATE OF MINNESOTA, County of At the corner location shown on th	
□	A REBAR WITH AN UNREADABLE CAP, IN THE
C/L OF THE GRAVEL [X] left monument as found, [ROAD OPPOSITE FENCE LINE RUNNING NORTH. lowered monument, removed monument (explain)
□ On set	
Sketch	of reference ties
FIELD -N-	FIELD
101st STREET	OUND CAPPED REBAR
N89°02'26"W, 2656.38' GRAVEL ROAD 64.3	S88'50'11"E, 2657.07' GRAVEL ROAD
SIGN POST	FIELD
E: 2 MN SOU	696,647.00 2,099,994.09 JTH ZONE, NAD 83 DT TO SCALE
Statement of evidence relative to this corner locat	tion is on back page
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER

N: 696,647.00 E: 2,099,994.09 MN SOUTH ZONE, NAD 83 NOT TO SCALE		
Statement of evidence relative to this corner location is on back page		
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. 5/22/06 Thomas Leff Date Registration No. 44563 Land Surveyor, Professional Engineer County Surveyor, County Engineer	OFFICE OF THE COUNTY RECORDER County of	

STATEMENT OF EVIDENCE:

NORTH 1/4 CORNER, SECTION 15, T. 106 N., R. 43 W.,

MURRAY COUNTY, MINNESOTA

1866

J.W. Bishop, US. Deputy Surveyor, monumented corner.

? Date

MN DOT R/W Map for Trunk Highway 30, calls for the 1/4 corner to be at the intersection of the trunk highway (east & west) and the fence running south.

3/22/2006

Ulteig Engineers, Inc., Survey Crew, Dennis Lavallie Party Chief, found a rebar with an unreadable cap, in the C/L of 101st Street.

Ties: SW-64.3' to steel, Sign post;

E-2657.07 to NE corner of Section 15; W-2656.38 to NW corner, Section 15.