

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


NORTH QUARTER Corner of Section 22, Township 105 N., Range 42 W., 5 th P.M.

STATE OF MINNESOTA, County of MURRAY

At the corner location shown on the sketch:

- On _____ found a _____
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 9/15/92 Placed a 3/4" X 24" REBAR WITH ALUMINUM CAP STAMPED
DATE
"MN DNR SURVEY MARKER," DOWN 1.0'

SKETCH OF REFERENCE TIES



1983 MURRAY COUNTY
COORDINATE SYSTEM
N = 116009.467
E = 471731.455

BEARINGS OBSERVED WITH COMPASS

Statement of evidence relative to this corner location is on back of page. 10/7/92
WMA01187.00.00.01

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Lowell R. Pommeroy 10-26-92
SIGNATURE DATE

Registration No. 17005

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of MURRAY

I hereby certify that this document was filed in the Co. recorders office at _____ .M. on the _____ day of OCT 27 1992 A.D., 19____

County Recorder James V. Johnson
By _____, Deputy

DOCUMENT NO. _____

North Quarter Corner Section 22, Township 105 North, Range 42 West

The DNR Bureau of Engineering contacted the following offices for information on this corner:

MN Secretary of State
Murray County Recorder and Highway Engineer
Moseng Land Surveying at Marshall
Madsen Land Surveying at Fairmont

- 1861 The U.S. General Land Office notes, on file in the Secretary of State's Office, show the corner marked with a post, made mound with trench and pits as per instructions.
- 1931 Surveyor's Record Book A, on file in the County Recorder's Office, on page 372, contains a survey that states; "Established Stone 10 x 10 x 16". Corner is shown to measure 2642.5 ft. from adjoining section corners. This information is also on file in the County Highway Engineer's Office.
- 1992 August 20, the DNR Bureau of Engineering hired a backhoe operated by Dudley Johnson of Johnson Ditching and Plumbing from Lake Wilson, to dig for evidence of the corner. Dug a 8 ft by 8 ft hole at the intersection of an east-west road and fence line south. Encountered a east-west strand of barb wire, down 1 ft, running along the center line of the road. Dug to a depth of three feet, but found nothing else. The intersection of fence and road was found to measure:
2642.85 ft from the northwest corner of Section 22
2641.99 ft from the northeast corner of Section 22

Analysis of the available information led the DNR Bureau of Engineering to conclude that the intersection of the east-west road and fence line south marks the location of the corner.