

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 29, Township 107N, Range 39W

5th Principal Meridian, State of Minnesota, County of MURRAY


At the corner location shown on the sketch:

On 8/27/2020 found a NO.5 REBAR WITH BROKEN CAP, 0.2' BELOW GRADE
DATE

left monument as found lowered monument removed monument (explain)

On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature *Jim Jones*

Date 6/16/2021 License No. 45874

Title:

- Land Surveyor Professional Engineer
 County Surveyor County Engineer

OFFICE OF THE COUNTY RECORDER

County of Murray

I hereby certify that this document was filed in the Co.

Recorder's office at _____ M. on the _____ day of _____ A.D. 20

County Recorder *Karen Brown*
 by JUN 22 2021, Deputy

DOCUMENT NO. _____

Statement of Evidence:

North Quarter Corner of Section 29, Township 107 North, Range 39 West, 5th Principal Meridian, Murray County, Minnesota.

July 1861 GLO Notes: Set post in mound

Feb. 2008 A survey in Section 20 by Perry Zieske shows a found iron monument at the corner.

Undated State Highway 30 plans (map file 12-9-002.tif) show the section corner at 49.4ft north of P.O.S.T. 663+45.9.

Sept. 2020 Westwood Professional Services searched and found No. 5 rebar with broken cap. Location fits 2008 Zieske Survey and offset from Highway plans. Accepted found monument and set references.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.