

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 31, Township 107N, Range 39W

5th Principal Meridian, State of Minnesota, County of MURRAY

At the corner location shown on the sketch:


On 11/3/2020 found a 6X6IN CONCRETE MONUMENT, DOWN 0.3FT  
DATE

left monument as found       lowered monument       removed monument (explain)

On 12/16/2020 placed a NO. 4 REBAR WITH CAP LS 45874 ON WEST SIDE OF MONUMENT, DOWN 0.3  
DATE

### SKETCH OF REFERENCE TIES

131ST ST



N.T.S.

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Handwritten Signature]

Date 6/16/2021 License No. 45874

Title:

- Land Surveyor       Professional Engineer
- County Surveyor       County Engineer

OFFICE OF THE COUNTY RECORDER

County of Murray

I hereby certify that this document was filed in the Co.

Recorder's office at \_\_\_\_\_ M. on the \_\_\_\_\_ day of \_\_\_\_\_ A.D. 20

County Recorder Karen Brown

by JUN 22 2021, Deputy

DOCUMENT NO. \_\_\_\_\_

Statement of Evidence:

North Quarter Corner of Section 31, Township 107 North, Range 39 West, 5th Principal Meridian, Murray County, Minnesota.

July 1861      *GLO Notes: Set post in mound*

May 1975      *Highway Department records show a concrete monument at grade.*

*Nail & cap in power pole                      SE      60.90ft*

*Nail & cap in post                                      N      34.95ft*

*Steel fence post                                      SW      46.60ft*

Dec. 2020      *Westwood Professional Services excavated with backhoe and found concrete monument. I set a 1/2" rebar with cap LS 45874 on the west side of the concrete monument as a witness to aid in future recovery of said monument, and set two reference ties.*

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.