	CERTIFI	CATE OF LOC	ATION	OF GO	VERNME	NT CC	DRNER	
NORTH QUARTER		Corner	of Section	06	_ , Township	107N	, Range	39W
5th Princi	pal Meridian, State	of Minnesota, County of	MURRAY					
At the cor	ner location shown	on the sketch:						
X	On 11/03/2020 found a 6x6" CONCRETE MONUMENT WITH "X" SCRIBED ON TOP. 0.2FT BELOW GRADE.							
	$oxed{X}$ left monument as found $oxed{\Box}$ lowered monument $oxed{\Box}$ removed monument (explain)							
X	X On 12/16/2020 placed a NO. 4 REBAR WITH CAP LS 45874 ON NORTH SIDE OF MONUMENT, DOWN 0.5FT							
		Sk	CETCH OF REF	FERENCE TIE	FS			
:	MAG NAIL IN SOU FACE OF POWER F			WIA WEST I	FACING SIGN		MAG NAIL II FACE OF PC 163°E - 67.56	N SOUTHEAST OWER POLE
								N.T.S.
		Statement of evidence	for this corn	er location	is on back of this	page.		
prepare	ed by me or under in declar in the declar in	ocument was researched my direct supervision and der the laws of the State	d that I am a of Minnesota.	Count I herel docum	E OF THE COUN  y of Murray  by certify that the  nent was filed in  der's office at	is the Co.	P.DER	
Title:	Surveyor	License No. 430		Count	day of y Recorder JUN 2 2	aren = 1 2021	A.D. 20	Deputy
☐ Count	y Surveyor	County Engineer		DOCU	MENT NO			

## JASON LATZKE Minnesota License No. 45874

## Statement of Evidence:

North Quarter Corner of Section 06, Township 107 North, Range 39 West, 5th Principal Meridian, Murray County, Minnesota.

No GLO Notes.

Undated, Survey record in Section 6 shows a concrete stone at the corner.

Undated, Survey record for Section 31 does not indicate what was found or set at the corner, but does show a distance of 2646.0ft to the Southeast corner of Section 31 and 2467.8ft to the Southwest corner of Section 31.

2020 December, Westwood Professional Services excavated with a backhoe and found a concrete monument down 0.5ft. I set a  $\frac{1}{2}$ " rebar and cap LS 45874 on the North side as a witness and to aid in future recovery of the monument.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.