CERTIFICATE OF LOCATION OF GOVERNMENT CORNER							
NORTH QUARTER	Corner of Section	9	_ , Township	107N	, Range	39W	
5th Principal Meridian, State of Minnesota, County of MURRAY							
At the corner location shown on the sketch.							
On 8/27/2020 found a NO. 4 IRON WITH CAP LS #44996, 0.2FT BELOW GRADE							
I left monument as found I lowered monument removed monument (explain)							
Onplaced a							
SKETCH OF REFERENCE TIES							
NO. 3 REBAR WITH REF. CAP				NO 3 RE	BAR WITH RI	FF CAP	
				10.511	0		
4	168 W		N72°E_ 				
171ST STREET 43.44 -							
				NO. 3	^ ⊖ REBAR WITH	REF. CAP	
N.T.S. Statement of evidence for this corner location is on back of this page.							
Statement of	f evidence for this corn	er location i	s on back of this	page.			
I hereby certify that this document was i prepared by me or under my direct supe		OFFIC	OFFICE OF THE COUNTY RECORDER County of Murray				
licensed Land Surveyor under the laws o	f the State of Minnesota						
			I hereby certify that this				
O - Po	_		document was filed in the Co.				
Signature The)		Recorder's office at .M. on the				
Date 6/16/2021 License	No. <u>45874</u>		-				
Title:			day of	(aren	A.D. 20	\	
	nal Engineer	by	IUN 2	2 2021		Deputy	
☐ County Surveyor ☐ County En			MENT NO.				

JASON LATZKE Minnesota License No. 45874

Statement of Evidence:

North Quarter Corner of Section 9, Township 107 North, Range 39 West, 5th Principal Meridian, Murray County, Minnesota.

- 1861 July, GLO Notes: Set $\frac{1}{4}$ post in mound
- 2016 May, Highway Department data shows that nothing was found with a metal detector at the corner.
- 2019 December, A survey in Section 9 by Jesse Zeig shows that he set a $\frac{1}{2}$ " iron pipe at the corner.
- 2020 September, Westwood Professional Services searched and found an iron with cap LS #44996 at the corner. I accepted the found monument and set reference ties.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.