

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 10, Township 107, Range 43, 5TH P.M.

STATE OF MINNESOTA, County of MURRAY


At the corner location shown on the sketch:

On _____ found a _____
DATE

left monument as found, lowered monument, removed monument (explain)

On 03-03-2006 placed a 1" IRON PIPE WITH SEAL #43844 (SEE BACK)
DATE

SKETCH OF REFERENCE TIES



Minnesota State Plane Coordinate
System Murray County Datum
NAD83 (1996)

N: 190173.169
E: 442969.813

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Samuel Bente 3/8/06
SIGNATURE DATE

Registration No. 43844

- Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER
County of _____

I hereby certify that this document was filed in the Co. Recorders office at _____ .M on the _____ day of MAR 14 2006 A.D. 20 _____

County Recorder *James V. Johnson*
By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence

In 1866, J. W. Bishop did the original subdivision of the township.

In December, 1954 the Minnesota Conservation Department found a 18" round stone with a 'x' chiseled on it, while doing a survey in Section 11-107-43.

In April, 1968 the DNR dug for the stone and found nothing. Between 1954 and 1968 the county rebuilt the road.

On March 3, 2006 Bueltel-Moseng Land Surveying reestablished the corner by retracing the DNR survey in the Southwest Quarter of Section 11-107-43. The corner fell in the center of the intersection. We set a 1" iron pipe with seal #43844 at the corner.