CERTIFICATE OF LOCATION OF GOVERNMENT CORNER								
NORTHEAST	Corner of Section		Township	107N	, Range	39W		
5th Principal Meridian, State of Minneson	ta, County of MURRAY							
At the corner location shown on the sket	ch:							
On 8/27/2020 found a NO. 5 REBAR WITHOUT CAP, 0.3FT BELOW GRADE								
I left monument as found	☐ lowered	monument	☐ re	emoved mor	nument (explo	ain)		
Onplaced	a							
<u></u>	SKETCH OF REF	FERENCE TIES						
MAG NAIL IN SOUTH FACE OF POWER POLE  NORTH EAST TELEPHONE F	CORNER OF	N7 11	0.37 0.37	0F P	NAIL IN SE FA OWER POLE )  ST STREET			
N.T.S.  Statement of evidence for this corner location is on back of this page.								
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.  Signature  Date 6 [16 2021 License No. 45874]		OFFICE OF THE COUNTY RECORDER  County ofMurray						
		document  Recorder's	I hereby certify that this  document was filed in the Co.  Recorder's office at, M. on the  day of					
☑ Land Surveyor ☐ Profess	by	by IUN 2 2 2021 , Deputy						
☐ County Surveyor ☐ County	ounty Surveyor			DOCUMENT NO				

## JASON LATZKE Minnesota License No. 45874

## Statement of Evidence:

Northeast Corner of Section 16, Township 107 North, Range 39 West, 5th Principal Meridian, Murray County, Minnesota.

No GLO Notes.

- 2013 December, Corner certificate by Perry Zieske for corners in Section 16 shows that he dug with a backhoe at the corner and found a  $6x10^{\circ}$  stone. Set  $\frac{5}{8}^{\circ}$  iron stake with cap LS 23008 and lists coordinates as listed: N: 184641.85 E: 564117.35
- 2020 September, Westwood Professional Services searched and found a No. 5 rebar at the corner. The coordinates fit with the 2013 corner record. I accepted the found monument location and set reference ties.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.