CERTIFICATE OF LOCATION	ON OF GOVERNMENT CORNER
NORTHEAST Corner of Section	18 ,Township 107 N ,Range 39 W , 5 th. P.
STATE OF MINNESOTA, County of MURRA	AY
At the corner location shown on the sketch	
□ Onfound a	
DATE	owered monument, 🗆 removed monument (explain)
On TO SURVEY MAR	4" REBAR WITH ALUMINUM CAP STAMPED KER", DOWN 0.4'
SKETCH O	F REFERENCE TIES
S 36°W 40.79' DNR NAIL & DISC SE SIDE POWER POLE UP 3'	NOTE: MONUMENT IS ON & N-S ROAD IN LINE WITH OLD FENCE 500' WEST IN LINE WITH & ROAD 500' EAST TWP RD. TWP RD.
983 MURRAY COUNTY DORDINATE SYSTEM	•
= 184,631.443 = 553,522.136	BEARING OBSERVED WITH COMPASS
Statement of evidence relative to this corner I	ocation is on beck of page J.B.M. 11 - 20 - 91 WMA 00065.00.00.01
hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE COUNTY RECORDER County of MARRAY
bejistration Ne	i hereby certify that this document was filed in the Co. Recorders office at M. on the day of Xana V xohnoon

11.MV1 1154 14 211

Northeast Corner of Section 18, Township 107 North, Range 39 West

The DNR Bureau of Engineering contacted the following for survey information:

Minnesota Secretary of State's Office Murray County Recorder's Office Murray County Highway Engineer's Office

- 1861 U.S. General Land Office notes obtained from the Secretary of State's Office show the corner marked with pits and mound.
- 1907 Surveyor's Record Book A, page 205, obtained from the County Recorder's Office contains a survey by J. W. Woolstencraft. Survey states that the government corner was found at corner. A description of a monument and a distance to it is not given.
- october, DNR Bureau of Engineering hired a backhoe to dig for evidence of a monument at corner. Dug a 10 foot north-south by 10 foot east-west by 2-1/2 foot deep hole the center being on the center line of a north-south road and in line with a fence west. No evidence of a monument was found. Set a DNR Survey Marker on the center line of the north-south road and in line with the fence west and found it to be:

in line with the westerly projection of the center line of road east 2645.77 feet from the north quarter corner of Section 18 2631.69 feet from the east quarter corner of Section 7

Analysis of the above information led the DNR Bureau of Engineering to conclude that the intersection of the center line of the north-south road and fence line west marks the obliterated position of the corner.