	CERTIFI	CATE OF	LOCATIO	N OF (GOVERNME	NT CO	RNER	
NORTHEAST		_ Corner of Section	20	, Township	107N	_ , Range	39W	
5th Princi	ipal Meridian, State	of Minnesota, C	County of MURRA	/				
At the co	rner location show	n on the sketch:						
On 8/27/2020 found a NO. 4 REBAR WITHOUT CAP FLUSH WITH ASPHALT								
	X left monume	nt as found	☐ lowe	red monur	nent 🗌	removed mo	onument (exp	olain)
	On	placed a _						
			SKETCH OF	REFERENC	E TIES			
		MAG NAII	TIN NE FACE 123.52	3.66.W 520°E 137.96	MAG NAIL IN NO	ORTH FACE	S.A.H. 11	N.T.S.
Statement of evidence for this corner location is on back of this page.								
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.				ota.	OFFICE OF THE COUNTY RECORDER County ofMurray			
Signature Jm Jm			do	I hereby certify that this document was filed in the Co. Recorder's office atM. on the				
Date	6/16/2021	License N	o. <u>45874</u>	Re				
Title:				Co	day of	aren -	A.D. 20	$\overline{}$
X Land	Surveyor	Profession	al Engineer	by	JUN	2 2 2021		Deputy
Count	ty Surveyor	☐ County Eng	gineer	De	OCUMENT NO			

JASON LATZKE Minnesota License No. 45874

Statement of Evidence:

Northeast Corner of Section 20, Township 107 North, Range 39 West, 5th Principal Meridian, Murray County, Minnesota.

No GLO Notes found.

May 1901	Survey record for Section 17 show a stone in grade.
April 1978	Survey record for Section 20 shows that the corner was dug with a backhoe and nothing found.
Nov. 1987	Highway Department records show that a $\frac{3}{4}$ " iron pipe was placed at the corner.
May 1999	C.S.A.H. 42 plans show the corner at PI station 1+610.639
March 2000	Highway Department records show a $\frac{3}{4}$ rebar was placed prior to the bituminous being laid.
Aug. 2006	A survey in Section 21 by Perry Zieske shows an iron monument at the corner. He lists the Murray County coordinates for the corner: N: 179318.54 E: 558853.26
Oct. 2015	A survey in Section 17 by Dennis Esplan shows a found iron monument at the corner.
Sept. 2020	Westwood Professional Services searched and found a No. 4 rebar, coordinates fit well to the 2006 Zieske survey.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.