

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 24, Township 106N, Range 42W

5th Principal Meridian, State of Minnesota, County of Murray.


At the corner location shown on the sketch:

☐ On _____ found a _____
DATE

☐ left monument as found ☐ lowered monument ☐ removed monument (explain)

☒ On 11/08/2021 placed a 1/2"X18" REBAR CAPPED "RLS 57085".
DATE

SKETCH OF REFERENCE TIES



N.T.S.

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature

[Signature]

Date 4-19-2022

License No. 57085

Title:

☒ Land Surveyor ☐ Professional Engineer
☐ County Surveyor ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of Murray

I hereby certify that this document was filed in the Co.

Recorder's office at _____ M. on the

22nd day of April A.D. 20 22

County Recorder Karen Brown

by _____, Deputy

DOCUMENT NO. _____

SETH WECKMAN
Minnesota License No. 57085

Statement of Evidence:

Northeast corner of Section 24, Township 106 North, Range 42 West, 5th Principal Meridian, Murray County, Minnesota.

- 1861 J.W. Myers, U.S. Deputy Surveyor, during the original public land survey a wood post was set, deposited charcoal and built mound of earth with trench and pits.
- 1901 J.W. Woolstencroft, survey shows a stake marked by previous survey.
- 2021 Westwood Professional Services searched the area and did not recover a monument. Lines of occupation consists of a North/South and East/West gravel roads. Holding the intersection of road centerlines as best available evidence of the corner location. The position agrees within reason of a computed lost position along the range line. Set a 1/2" x 18" rebar with a cap marked "RLS 57085" and established 3 local reference ties.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument set is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.