	CERTIFICATE O	F LOCATION	OF GO	VERNME	NT CC	RNER	
NORTHEAST		Corner of Section	31	, Township	107N	_ , Range39	w
5th Princ	ipal Meridian, State of Minnesota,				1		
At the co	rner location shown on the sketch	:					
X	On <u>8/27/2020</u> found a <u>IRON WITH ILLEGIBLE CAP DOWN 0.3FT</u>						
	X left monument as found	lowered monument removed monument (explain)					
	Onplaced a						
		SKETCH OF REF	FERENCE TIE	S			
	SE CORNER OF TELEPHONE PED	SESTAL AVE		N60°E 64.76	FND NAIL OF CORN	. W/ BOTTLE CAP S ER POST	FACE
			FF	ND NAIL W/ BO	TTLE CAP NE	131ST ST	N.T.S.
	Statement (of evidence for this corn	er location is	on back of this	s page.		77.7.51
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota. Signature Date 6 16 12021 License No. 45874		OFFICE OF THE COUNTY RECORDER County of Murray					
		No. <u>45874</u>	docum Record	y certify that then the sent was filed in the series office at day of	n the Co.		
Title:	Cunguar Duction	anal Engineer		JUN 2 2	2021		v ifv
-	Surveyor	nal Engineer Ingineer	by	MENT NO.		, Dep	uty

JASON LATZKE Minnesota License No. 45874

Statement of Evidence:

Northeast Corner of Section 31, Township 107 North, Range 39 West, 5th Principal Meridian, Murray County, Minnesota.

MAY 15, 1975 - HWY DEPT RECORDS SHOW A CONCRETE MONUMENT 10" BELOW GRADE.

OCT. 11, 1985 - HWY DEPT. RECORDS SHOW A FIELD STONE AND PLACED BROKEN CONCRETE BLOCK ON TOP. N&C IN FENCE POST NNE 63.86; N&C IN FENCE POST NE 60.68; N&C IN PP SE 41.68.

MARCH 7, 2005 - HWY DEPT RECORDS SHOW THEY FOUND IRON STAKE W/ CAP BY ZIESKE LAND SURVEYING.

SEPTEMBER 2020 - WESTWOOD PROFESSIONAL SERVICES SEARCHED AND FOUND IRON W/ ILLEGIBLE CAP AND 2 TIES FROM 1985 HWY DEPT RECORDS, WHICH FIT WELL. ACCEPTED MONUMENT AND SET ADDITIONAL REFERENCES.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.