| CERTIFI | CATE OF LOCA | TION | OF GO | VERNME | NT CO | RNER | | |
|---|---|--|--|--|-----------------|-------------|---------|--|
| NORTHEAST | Corner of . | Section | 9 | , Township | 107N | , Range | 39W | |
| 5th Principal Meridian, State | | | | | | | | |
| At the corner location show | n on the sketch: | | | | | | | |
| X On <u>8/27/2020</u> DATE | On 8/27/2020 found a NO. 4 REBAR WITH CAP LS #12967, DOWN 0.3FT DATE | | | | | | | |
| X left monume | nt as found | lowered | monument | □ <i>r</i> | emoved mo | nument (exp | lain) | |
| On | placed a | | | | | | | |
| SKETCH OF REFERENCE TIES | | | | | | | | |
| NO. 3 REBAR WIT | TH REF. CAP O N729W 50.35 | CONTRACTOR AVENUE | \$30°E \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | 171: | ST STREET | | |
| | MAG NAIL IN TOP WEST END OF 15" CMP | | | MAG NAIL IN TO END OF 15" CM | | | N.T.S. | |
| Statement of evidence for this corner location is on back of this page. | | | | | | | | |
| I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota. | | OFFICE OF THE COUNTY RECORDER County ofMurray | | | | | | |
| Signature | License No. 45874 | <u> </u> | docume | y certify that the ent was filed in er's office at day of Recorder | the Co. | A.D. 20 | <u></u> | |
| ☒ Land Surveyor | ☐ Professional Engineer | | by | JUN | 2 2 2021 | | Deputy | |
| ☐ County Surveyor | ☐ County Engineer | | DOCUI | MENT NO | | | | |

JASON LATZKE Minnesota License No. 45874

Statement of Evidence:

Northeast Corner of Section 9, Township 107 North, Range 39 West, 5th Principal Meridian, Murray County, Minnesota.

No GLO Notes.

- 1913 June, Survey record for Section 3 shows a big fence post at the corner.
- 1980 October, LS #12967 found a blue granite stone at the corner and placed a $\frac{1}{2}$ " iron and cap #12967 above it.
- 2016 May, Highway Department data shows that an iron with cap #12967 was found. They listed the coordinates of: N: 189922.51 E: 564063.02
- 2020 September, Westwood Professional Services searched and found an iron with cap LS #12967 at the corner. Coordinated fit with the 2016 Highway Department data. The found monument was accepted and set reference ties.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.