CERTIFICATE OF LOCATION OF GOVERNMENT CORNER							
NORTHWEST		_ Corner of Section	1	_ , Township	107N	, Range	40W
5th Principal Meridian, State of Minnesota, County of MURRAY							
At the corner location shown on the sketch:							
X On 8/26/2020 found a NO. 8 REBAR WITHOUT CAP DOWN 0.6FT DATE							
X lef	Ieft monument as found Iowered monument removed monument (explain)						
□ On <u> </u>	DATE placed a _						
SKETCH OF REFERENCE TIES							
	MAG NAIL	IN NE FACE	SIGN S	I POST)			
- 12 Mar. 12							
							1ST STREET
		230TH AVE	NO.3 RE	BAR WITH REF. C	A <i>P</i>		
N.T.S.							
I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota. Signature			OFFICE OF THE COUNTY RECORDER County of Murray I hereby certify that this document was filed in the Co.				
							Date 6/16)
Title:			County	y Recorder	aren [<u>Srowy</u>	
X Land Surveyor	Profession	al Engineer	by	JUN 2 2	2021		Deputy
☐ County Survey	yor 🔲 County Eng	gineer	DOCU	MENT NO.			

JASON LATZKE Minnesota License No. 45874

Statement of Evidence:

Northwest Corner of Section 1, Township 107 North, Range 40 West, 5th Principal Meridian, Murray County, Minnesota.

HISTORY: GLO - JULY, 1861

NOVEMBER 22, 1928 - SURVEY RECORD FOR SECTION 2 SHOWS A CONCRETE STONE AT THE CORNER.

APRIL 23, 1932 - SURVEY RECORD FOR SECTION 35 SHOWS A STONE IN GRADE.

JULY 21, 1989 - HWY DEPT RECORDS SHOW THAT THEY LOCATED A CONCRETE MONUMENT ABOVE A STEEL SHAFT. PLACED 1" X 11" REBAR ABOVE STEEL SHAFT.

AUGUST 27, 2013 - HWY DEPT RECORDS SHOW THAT THEY LOCATED A 3/4" REBAR AND LIST THE COORDINATES N 195148.08 E 543072.08

SEPTEMBER 2020 - WESTWOOD PROFESSIONAL SERVICES SEARCHED AND FOUND A 3/4" REBAR. COORDINATES FIT HWY DEPT DATA. ACCEPTED FOUND MONUMENT AND SET REFERENCES.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.