CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
<u>South 1/4</u> of Section <u>24</u> , Township <u>107N</u> , Range <u>41W</u> , <u>5th</u> P.M. STATE OF MINNESOTA, County of <u>Murray</u>	
At the corner location shown on the sketch On <u>9/30/08</u> found <u>5/8" Iron Stake</u>	
🗌 left monument as found 🗌 lowered monument, 🛛 removed monument (explain)	
On <u>10/06/08</u> placed a <u>1" iron pipe with yellow plastic survey cap number 23008</u>	
SKETCH OF REFERENCE TIES	
35.09	
34.34 - SOUTH 1/4 COR. SEC. 24-107-41 SURVEY MARKER SPIKE IN POWER POLE	
<u>S 1/4 COR. COORDINATES</u> 174015.34 N 514013.49 E MURRAY COUNTY COORDINATES NAD 83 (2007)	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.	OFFICE OF THE COUNTY RECORDER
<u>Lerry</u> <u>L. Juspe</u> <u>10-23-08</u> SIGNATURE DATE MN. LICENSE NO. 23008	I hereby certify that this document was filed in the Co. Recorder's Office at on the day of OCT 2.8 2008
MN. LICENSE NO. 23008	County Recorder <u>Ames V. Johnson</u> By, Deputy DOCUMENT NO

Statement of Evidence

Original Township Plat indicated the subdivision was surveyed by G.M. Fletcher with date of contract of July 11th 1861.

Murray County Highway Department had no information on this corner.

On 9/13/2008 we found a 5/8" Iron Stake. We removed stake and dug 10' X 20' X 4.5' deep hole with backhoe and found nothing. We placed 1" iron pipe with yellow plastic survey cap number 23008 at the location of the 5/8" Iron Stake.

23008 Peny L. Zieske 10-23-08

PAGE 2 OF 2