	Index No.
CERTIFICATE OF LOCATION OF GOVERNMENT CORNER SOUTHWEST Corner of Section 16, Township 106, Range 43, 5th P.M. STATE OF MINNESOTA, County of MURRAY At the corner location shown on the sketch: On 3/22/2006 found BENT REBAR @ INTERSCETION OF ROADS. left monument as found, lowered monument, removed monument (explain) 3/22/2006 set 5/8" REBAR WITH CAP: RLS 44563.	
Sketch of reference ties	
FIELD CHISELED "X" ON TOP WEST END 36" RCP 91st STREET GRAVEL ROAD	FIELD THE MEASURED FROM TOP CENTER TP BOX 900
89 ⁵ /	FOUND BENT REBAR REPLACED SAME WITH 5/8" REBAR W/ CAP RLS 44563 91st STREET GRAVEL ROAD
FIELD ELECTRICAL TRANSFORMER MEASURED FROM TOP NE CORNER BOX N: 691, E: 2,091, MN SOUTH ZO NOT TO	955.81 NE, NAD 83
Statement of evidence relative to this corner location is on back page	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. A	OFFICE OF THE COUNTY RECORDER County of

DOCUMENT NO. _

☐ County Surveyor, ☐ County Engineer

STATEMENT OF EVIDENCE:

SOUTHWEST CORNER, SECTION 16, T. 106 N., R. 43 W.,

MURRAY COUNTY, MINNESOTA

1866

J.W. Bishop, U.S. Deputy Surveyor, monumented corner.

8/2/1927

Murray Co., Found stone in grade, Ties: NW-45.5' to fence corner; NE-35.0' to fence corner; SE-103.2' to highline pole; S-29.0' to line of poles.

3/22/2006 Ulteig Engineers, Inc., Survey Crew, Brian Payne Party Chief; found bent rebar at intersection of gravel roads; replaced same

with 5/8" rebar with cap: RLS 44563.

Ties: NW-38.1' to chiseled "X" on top, west end, of 36" RCP.;

NF-58.8' to top, center of telephone pedestal:

NE-58.8' to top, center of telephone pedestal; SW-69.5' to top, NE corner of electrical transformer box;