Corners to be Indexed SW 34-105-41 S1/4 34-105-41 W1/4 34-105-41 I hereby certify that this document and the data		FEB 1 4 2023 Karen Brown	
contained herein was prepared by my direct supervision. Daniel L. Bueltel License No. 43844	1/14/2023 Date		
CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
Land survey monuments situated in Section 34 ,Township 105 ,Range 41 ,5TH P.M. STATE OF MINNESOTA, County of MURRAY			
28 105 A1	26	-105-41	26-105-41
N: 105341.500 E: 500684.870 CAPPED IRON	N: 105346.230 E: 503363.150 2678.28' CAPPED IRON 2676.03'		N: 105353.400 E: 506039.170 CAPPED IRON
33-105-41 N:102684.293 E:500716.885 5/8" IRON W/SEAL #43844 FOUND MONUMENT O SET MONUMENT N:100042.730 E:500748.712 5/8" IRON W/SEAL #43844	N 89.23,26, E	\$ 89.50,47" W *	N: 102680.912 35-105-41 E: 506035.178 CONC. MONUMENT 9 1. 100006.753 E: 506038.120 CAPPED IRON
Murray County Coordinate System (1996 Adj.)			

Statement of Evidence

SW 34-105-41

On May 4, 2022 Bueltel-Moseng Land Surveying dug with backhoe found no evidence of the corner. Set a $\frac{5}{8}$ " iron with seal #43844 in the center of the road intersection.

S1/4 34-105-41

May 19, 1925, old survey shows corner to be 58.7 feet north and 258.5 feet west of NE corner of section 4-104-41, and also midway between section corners.

On May 4, 2022 Bueltel-Moseng Land Surveying searched and found no evidence of the

Set a $\frac{5}{8}$ " iron with seal #43844 on line between section corners and in line with the well established fence line running north. Fence is within 2-3 feet of midway. Corner is also 278 feet west and 50.7 feet north of NE corner of section 4-104-41.

W1/4 34-105-41

On May 4, 2022 Bueltel-Moseng Land Surveying searched and found no evidence of the corner. Set a $\frac{5}{8}$ " iron with seal #43844 on line between section corners and in line with the well established fence lines running to the east and to the west.

E1/4 34-105-41

February 5, 1934, concrete monument

On May 4, 2022 Bueltel-Moseng Land Surveying found concrete monument.