


# MURRAY COUNTY.

Section 12

10798 McMill-Warner Co., Blank Book Manufacturers, St. Paul.

Township 105

Range 41



12  
13  
14  
15  
16  
17

18  
19

20  
21

22  
23

24  
25

26  
27

28  
29

30  
31

32  
33

34  
35

"D" "Bridge spike" R.P. Bottle cap cor. post S. 50.2';  
R.P. Edge of steel fence post S.W. 57.2' (1956)

"D" "Bridge spike" R.P. Bottle cap cor. post N.E. 43.6';  
R.P. Bottle Cap cor. post S.E. 59.8'

"F" "2x2 Hub" R.P. Bottle cap cor. post S. 50.8'; R.P.  
Bottle cap in third wood post S.E. 68.9' (1956) S.W.

located 2x2 Hub - dug 9' below road grade with backhoe;  
Did not locate stake as mentioned on Sec 18-105-40 - Placed  
18" steel pin above 2x2 hub location (hub removed) near road  
grade: R.P., N&C, cor. post W. 51.57'; R.P., N&C, third fence  
post S.W. 46.39'; R.P., N&C Fence post N.E. 56.46'; R.P., N&C, T.P.,  
N.E. 66.05' - Nov. 1, 1974