


MURRAY COUNTY.

Section 17
 McGinn Warner Co., Blank Book Manufacturers, St. Paul.

Township 108

Range 39



- O. Indicate gov. cor. See Page 240
- F. "Concrete Stone": R.P. Tack in cor fence post west 40°: R.P. Tack in Tel pole SW. 66.5' Fence Line 1 ft. North of Cor.
- E. "Concrete Stone": R.P. Tack in Cor. fence post SW. 45°: R.P. Tack in 3rd fence post North of Cor post N.W. 41.2 Cor. 30' North of fence line.
- C. Found field stone 2' below grade, Placed 1/2" x 18" Iron pin over stone. sept 77
- PP top center of tract. 4260 S.E. Only tie available. sept 77
- S. Dig hole 6' x 6' x 6' with backhoe found nothing.

16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35

SURVEY No. _____

Section 17 Town 108 Range 39



FIELD NOTES.

o Indicates Gov't corners.

see pge. 240.