

MURRAY COUNTY.


Section 29

10798 McGill-Warner Co., Blank Book Manufacturers, St. Paul.

Township 106

Range 42

Stone 30
463
Cor F.P.



"G" Stone Tack in Cor fence post South 30° : R.P. Tack in Cor fence post North 33° : R.P. Tack in fence post NW 41°
 "H" Stone R.P. Tack in Cor fence post N.E. 45° : R.P. Tack in Cor fence post West 33° : R.P. Tack in Cor fence post S.E. 46°
 F.A. March.
 "I" Stone : R.P. Tack in tel pole S.E. 54° : R.P. Tack in Cor fence post NE 38° : R.P. Tack in N.W. Cor fence post 45°
 "E" Stone R.P. Tack in brace post S.E. 39° : R.P. Tack in Cor fence post East on Line 35°
 J. Sorenson 6-4-77
 "G" Located original field stone 1.8' below gravel road top; Placed 1/2" x 1-1/2" steel pin above; R.P. N&C. P.P. N.E. 84.76'; R.P. N&C. Fence Post N. 44.92'


28
29
30
31
32
33
34
35
36

SURVEY No. _____

Section 29

Town 106

Range 42



FIELD NOTES.

"G" Stone Tack in Cor. fence post South 30³' : R.P. Tack in Cor post
 North 33⁶' : R.P. Tack in fence post N.W. 41²'
 "H" Stone R.P. Tack in Cor fence post N.E. 45³' : R.P. Tack in Cor fence
 post West 33²' : R.P. Tack in Cor fence post S.E. 46²' : F.A. March