



East Quarter Corner of Section 19, Township 105 North, Range 41 West

The DNR Bureau of Engineering contacted the following for survey information:

Minnesota Secretary of State's Office  
Murray County Recorder's Office  
Murray County Highway Engineer's Office  
Madsen Land Surveying of Fairmont

- 1861 U.S. General Land Office notes obtained from the Secretary of State's Office show the corner marked with a wood post in a mound with trench and pits as per instructions.
- 1931 Surveyor's Record Book A, page 365, obtained from the County Recorder's Office, contains a survey, surveyor not indicated. Survey shows that an old corner stone was found at corner. The corner is shown:
- 6 inches east of a fence post
  - in line with fences east and west
  - 2639.1 feet from the northeast corner of Section 19

The above information is also contained in a Surveyor's Record Book obtained from the County Highway Engineer's Office.

- 1966 May, DNR Bureau of Engineering found a stone at corner. The stone was found to be:
- 6 inches east of a corner fence post with fences north, south, east and west
  - 2634.8 feet from the northeast corner of Section 19
- 1968 January and June, DNR Bureau of Engineering found the stone at corner.
- 1996 May 20, DNR Bureau of Engineering found a 10 inch by 12 inch by 12 inch stone flush with the ground at corner. The stone was found to be:
- 0.5 of a foot east of an old downed north-south fence
  - in line with the westerly projection of an east-west field division 600 feet east
  - 2638.68 feet from the northeast corner of Section 19

Analysis of the above information led the DNR Bureau of Engineering to conclude that the found stone marks the location of the corner.