

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


East Quarter Corner of Section 8, Township 107, Range 39, 5TH P.M.

STATE OF MINNESOTA, County of Murray

At the corner location shown on the sketch:

- On 5/7/2025 found a 1/2" iron at the surface of the road.  
DATE
- left monument as found,  lowered monument,  removed monument (explain)
- On \_\_\_\_\_ placed a \_\_\_\_\_  
DATE

### SKETCH OF REFERENCE TIES



Murray County  
 Coordinate System NAD83 (1996)  
 N: 187258.170  
 E: 558809.900

WGS84  
 LAT: 44°05'13.8650"  
 LON: -95°32'34.3127"

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

  
 Daniel L. Bueltel  
 License No. 43844  
2/10/2026  
DATE

**MURRAY COUNTY RECORDER**  


FEB 17 2026

## Statement of Evidence

East Quarter Corner Section 8, T107N, R39W of the 5th P.M.

In July of 1861, J.W. Myers surveyed the township lines.

In September of 1861, L. Brockmann subdivided the township.

Survey record dated April 13, 1978 notes a field stone was found 3.4' below grade and steel pin was placed above stone.

A corner certificate Lyle Moseng, L.S. 11943, dated June 13, 1991 notes he set a  $\frac{5}{8}$ " iron with a seal on line between the section corners and at proportionate distance.

C.S.A.H. 42 plans from May of 1999 shows the corner position at PI station 4+030.965

County records dated March of 2000 notes a  $\frac{3}{8}$ " iron placed at the corner.

County records dated May of 2017 shows a No. 4 rebar placed at the corner.

In September of 2020 Westwood Professional Services found a No. 4 rebar at the corner.

On May 5, 2025 Bueltel-Moseng Land Surveying found a  $\frac{3}{8}$ " rebar at the corner. The previous ties from 2020 checked. Accepted corner.