

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 27, Township 108 N., Range 40 W., 5th P.M.

STATE OF MINNESOTA, County of MURRAY


At the corner location shown on the sketch:

- On _____ found a _____
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 7-1-85 placed a 1 1/4" x 1 1/4" x 20" PERFORATED STEEL TUBE WITH
DATE
ALUMINUM CAP STAMPED "D.N.R. SURVEY MARKER", FLUSH

SKETCH OF REFERENCE TIES



NO TIES AVAILABLE



Statement of evidence relative to this corner location is on back of page.

J.B.M. 7-11-85
G-361

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Lawell R. Pommeroy Jr. 7-22-85
SIGNATURE DATE

Registration No. 170057

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER **172141**
County of Murray

I hereby certify that this document was filed in the Co. Recorders office at 10 .M. on the 30th day of July A.D., 19 85

County Recorder Henry J. Ohme

By _____, Deputy

DOCUMENT NO. 172141

North Quarter Corner Section 27, Township 108 North, Range 40 West

This corner was originally established by the U. S. General Land Office survey in 1861. The government notes show corner marked with a wood post set in mound of earth with pits and trench dug around the mound.

In October 1984, the DNR Bureau of Engineering contacted the Murray County Offices of the Recorder and Highway Engineer.

No resurvey information was obtained on this corner.

In October 1984, the DNR Bureau of Engineering traversed to the area of the corner and located an east-west fence. Searched an area 2640 feet from the northeast corner of Section 27 and on the east-west fence but found nothing. GLO established this corner on a true line from the northeast corner of Section 27 at a distance of 2640 feet. The true line continued out to the lake where a meander corner was set at 4507.8 feet. Being no evidence of a monument could be found the corner was re-established at a distance of 2640 feet from the northeast corner of Section 27 and on the east-west fence line.

Accept this position as the location of the corner.

Traverse information is available from the DNR Bureau of Engineering.

recl4/missu2