

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 23, Township 108N, Range 39W

5th Principal Meridian, State of Minnesota, County of MURRAY


At the corner location shown on the sketch:

On 9/01/2020 found a SURVEY MARKER/SPINDLE WITH TOP BROKEN OFF, FLUSH AT SURFACE.
DATE

left monument as found lowered monument removed monument (explain)

On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



N.T.S.

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Handwritten Signature]

Date 6/17/2021 License No. 45874

Title:

- Land Surveyor Professional Engineer
- County Surveyor County Engineer

OFFICE OF THE COUNTY RECORDER

County of Murray

I hereby certify that this document was filed in the Co.

Recorder's office at _____ M. on the _____ day of _____ A.D. 20 _____

County Recorder Karen Brown
by JUN 22 2021, Deputy

DOCUMENT NO. _____

Statement of Evidence:

Northeast Corner of Section 23, Township 108 North, Range 39 West, 5th Principal Meridian, Murray County, Minnesota.

No GLO Notes.

1887 *July, Survey record for Section 23 shows that the government corner was found.*

Undated, Highway Department records show that they excavated with a backhoe and found nothing.

2003 *April, Road plans for CSAH 45 show the corner was assumed at PI station 207+61.10.*
Coordinates: N: 211121.98 E: 574574.59.

2011 *June, Corner Certificate by Perry Zieske shows that he set a monument with cap LS 23008 at the corner. County*
Coordinates: N: 211121.77 E: 574575.73

2020 *September, Westwood Professional Services searched and found a $\frac{1}{2}$ " iron, possible a survey marker or spindle with the top broken off, and no cap. Found all 3 ties from 2011 Corner Certificate which fit well to the found monument.*

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.