NORTHWEST 06 , Township 107N , Range \_ Corner of Section \_ 5th Principal Meridian, State of Minnesota, County of Murray At the corner location shown on the sketch: 3/8" rebar with illegible cap 0.2' deep and 2 ties of previous records plus one tie of X On \_\_\_\_11/11/2022 \_ found a\_ unknown origin. removed monument (explain) X left monument as found lowered monument placed a\_ SKETCH OF REFERENCE TIES FOUND MAG NAIL IN S FACE OF PP FOUND MAG NAIL IN W FACE OF PP FOUND MAG NAIL IN NE FACE OF LONE POST Statement of evidence for this corner location is on back of this page. I hereby certify that this document was researched and OFFICE OF THE COUNTY RECORDER prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota. County of Murray JAN 0 5 2023 I hereby certify that this document was filed in the Co. Recorder's office at .M. on the 56488 License No. day of County Recorder Title: ☑ Land Surveyor Professional Engineer └└County Surveyor ☐ County Engineer DOCUMENT NO.

пdе		A-	
ากเ	7 <i>Y</i>	Δ-	- 1

## KYLE JOHNSON Minnesota License No. 56488

## Statement of Evidence:

Northwest Corner of Section 06, Township 107 North, Range 43 West, 5th Principal Meridian, Murray County, Minnesota.

- 1861- GLO set a post, mound of earth with trench and pits and charcoal.
- 1901- Survey of Section 31 shows a distance of 2660 to the NQ of Section 6.
- 1936- Surveyors Record Book survey of section 33 notes a concrete stone and notes 3 ties.
- UNKN- Survey in section 6 shows a distance from the NW to the NE of section 6. does not state what was found or set.
- 2007- Chris Moehrl, LS40853, filed a corner record stating he found a 8x8 marked stone and set a 3/8" rebar with cap over the top. Notes 4 ties.
- 2022- Westwood Professional Services found a 3/8" rebar with illegible cap 0.2' deep and 2 ties of previous record. and 1 tie of unknown origin. Distances agree with previous survey of Section 6.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.