


# MURRAY COUNTY.

Section 1  
 10798 McGill-Warner Co., Blank Book Manufacturers, St. Paul.

Township 106

Range 41



- "C" "Found Stone" Placed stone on top: R.P. Tack in cor. fence post North 32<sup>1</sup>/<sub>2</sub>: R.P. Tack in fence post NE. 41<sup>5</sup>/<sub>8</sub>: R.P. Tack in cor. fence post south 33<sup>5</sup>/<sub>8</sub> F.A. March 1934
- "D" "Concrete Stone": R.P. Tack in tel pole N.W. 42<sup>2</sup>/<sub>8</sub>: R.P. Tack in cor. fence post SW 44<sup>2</sup>/<sub>8</sub>
- "E" "Concrete Stone" R.P. Tack in fence post Easton Line 32<sup>2</sup>/<sub>8</sub>: R.P. Tack in fence post NE 41<sup>2</sup>/<sub>8</sub>
- "F" "Concrete Stone" R.P. Tack in tel pole N.W. 44<sup>6</sup>/<sub>8</sub>: R.P. Tack in cor. fence post SW 43<sup>6</sup>/<sub>8</sub> F.A. March 1934

1969


F. Iron Rod R.P. N & C. in R.P. 58.22' N.W.  
 N & C. Cor. Post. S.W. - 59.30'  
 N & C. in Yield Sign 50.44' NE  
 T.P. N.W. - 40.80' 58.35'  
 "X" on Culv. Not. Apron - 40.80' NW  
 - 41.30' SW'

E. Iron Rod. R.P. "X" on Apron W - 39.65'  
 SW - 51.10'  
 N & C P.P. SE - 54.00'

□, Iron Rod R.P. N & C. P.P. SE - 59.85'  
 "X" on Apron NW - 44.30' SW - 43.45'

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36

SURVEY No. \_\_\_\_\_

Section 1 Town 106 Range 41

## FIELD NOTES.

"C" "Found Stone" Placed stone on top R.P. Tack in cor fence post  
 North  $32^{\circ}$ : R.P. Tack in fence post NE  $41^{\circ}$ : Tack in cor fence post  
 South  $33^{\circ}$  1934 F.A. March.