


# MURRAY COUNTY.

Section 17  
 10798 McGill-Warner Co., Blank Book Manufacturers, St. Paul.

Township 105

Range 42



16  
17

18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36


Nov 9-1912  
 B. see sec 18  
 "C" Dog huge hole found nothing: April-1977  
 D.  
 E. established  
 F. established  
 G. large grey rock on cor. 20'; net line N. to F.  
 H. see sec 18  
 I. " " "  
 J. N. Hostettersoft  
~~"B" Stone" R.P. Tack in cor. fence post N.E. 474' R.P. Tack in~~  
~~top fence post East of Brace post E. 642'~~  
~~"C" Conc. Monument 5" below Roadtop R.P. N. & C. in P.P. 68.10' N.W.~~  
~~"E" Stone" : R.P. Tack in blazed fence post N.E. 412' R.P. Tack in~~  
~~blazed fence post S.E. 222' : Bottom of Bridge Rail S.W. 222' : Bottom of Bridge Rail S.E.~~  
 "D" Located Concrete Monument 1'-6" below Grade: April-1977  
 R.P. N&C in t.e.t 6.E. 43.16, N&C Brace Pole N.E. 45.37, N&C P.P.N.W. 48.72  
 "F" Located Concrete Monument 8" below Grade: April 1977  
 Monument is 45' south of intersection: R.P. N&C in P.P. N.W. 51.45  
 N&C in t.e.t N.E. 41.50

Checked "t" Top of Culv. 22.82' W.  
 Checked "t" Top of Culv. 55.65' SE.



SURVEY No. 1111

Section 17 Town 105 Range 42



FIELD NOTES.

Nov. 9, 1912.

B See sec 15.

C

D

E Established

F Established

G Large grey rock on cor. 20.5' not line H to F.

H See sec. 15.

I " " "

*J. W. Woodlawn*