


SURVEYOR'S RECORD

Section 26

Township 107

Range 43



"B" Stone: R.P. Tack in cor. fence post NE 46°; R.P. S.E. Cor. of south Bridge Rail west of stone 45°.

"I" Stone: R.P. Tack in cor. fence post East on Line 39°; R.P. Tack in fence post SW 39°.

"I" Iron Bolt 3/4" x 18" w/ "X" on top (No ties - 2x2 hub 100' & 200' East on line.) Oct. 1969

"B" Stone	R.P. S.E. Cor. of SE. Bridge Wing	42.35
		41.65
April-1977	R.P., N&C, West Post South	37.10
		36.8
	R.P., N&C, Fe. Post, NE.	41.70
		41.3

~~"E" Dig huge hole but found nothing. April 1977~~

26
27