


# MURRAY COUNTY.

Section 35  
10785 McGill-Warner Co., Blank Book Manufacturers, St. Paul.

Township 106

Range 42



"c" Placed Concrete Stone": R.P. Tack in Cor fence post NW 47<sup>3</sup>: R.P. Tack in Cor fence post SW 46<sup>8</sup>

"D" Placed Concrete Stone": R.P. Tack in Cor fence post south 34<sup>8</sup>: R.P. Tack in Tel pole SE 44<sup>8</sup>

"B" Concrete Stone": R.P. Tack in Cor fence post SW 46<sup>1</sup>: R.P. Tack in Cor fence post SE 47<sup>4</sup>

"C" Concrete Stone": R.P. Tack in Cor fence post SW 47<sup>5</sup>: R.P. Tack in Cor fence post NW 74<sup>8</sup>: R.P. North Edge of Culvert NW 58<sup>2</sup> "1940"

"C" Placed steel pin in bituminous mat July 6, 1973: R.P. N&C, P.P. N.E. 78.68; R.P. N&C, P.P. S.E. 72.31; R.P. N&C, T.C.T. SW 59.65

"A" Located large field stone 1.7' below oil mat March 22, 1973:

Placed steel pin in 3" bituminous overlay July 6, 1973: R.P. N&C. Cor. Post fence line East 41.78; R.P. N&C. Fence Post N.E. 53.74; R.P. steel Fence Post (Painted Red) N.W. 63.23

"G" Located painted field stone 2.5' below oil mat March 22, 1973:

Placed steel pin in 3" bituminous overlay July 6, 1973: R.P. N&C. Cor. post N.E. 64.89; R.P. N&C. Gate Post W.N.W. 67.70; R.P. N&C. Gate post N.N.W. 58.85

34  
35  
36